



RENAULT

HNI8CRF

report date: 2024-03-29

General information

Make	RENAULT
Model	CLIO DYNAMIQUE NAV
Colour	Black
Year of manufacture	2018
Top speed	104 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	72 BHP
Max. torque	107 Nm at 4.250 rpm
Engine capacity	1.149 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	50.4 mpg
CO2 emission	127 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-07-21
Pictures	18
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-07-24
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	12
Total items failed	4

MOT #5	2023-07-25 14:39
MOT test number	535649925916
Result	✓ Passed
Next expiry date	2024-07-24
Advice	Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #4	2023-07-25 09:27
MOT test number	141322898868
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Fail	Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #3	2022-04-02 09:26
MOT test number	460279587903
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #2** 2022-03-28 10:08**MOT test number** 241244134357**Result** ✗ Failed**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))**MOT #1** 2021-03-27 10:48**MOT test number** 990861013115**Result** ✓ Passed**Advice** Front Brake disc worn, but not excessively both (1.1.14 (a) (i))**Advice** Nearside Front Inner Road wheel slightly distorted rim (5.2.2 (c) (i))**Advice** Oil leak, but not excessive oil filter area (8.4.1 (a) (i))**Advice** Offside Rear Outer Tyre has a cut but not deep enough to reach the ply or cords sidewall (5.2.3 (d) (i))



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
24 July 2024

Tax status	Valid until 1 February
Days left	277
MOT expiry date	24 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	HN18CRF
Plate since	2019-03-29
Current registration	HN18CRF
Plate since	2019-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-03-28
Last registration	2023-07-25
Complete history	See info



Registration #1	2018-03-28	27 mi
Registration #2	2021-03-27	29.006 mi
Registration #3	2022-03-28	39.433 mi
Registration #4	2022-03-28	39.433 mi
Registration #5	2023-07-25	39.433 mi
Registration #6	2023-07-25	39.433 mi
Registration #7	2023-07-25	39.433 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	89%
Pedestrian	66%
Safety systems	99%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1732 mm
Height	1448 mm
Length	4063 mm
Wheel base	2589 mm
Kerb weight	1059 kg
Max. allowed weight	1564 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	FC45511