



report date: 2024-03-29

General information

Make	MINI
Model	MINI (R58) COOPER
Colour	White
Year of manufacture	2009
Top speed	123 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	48.7 mpg
CO2 emission	129 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-07-01
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-23
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	38
Total items failed	0

MOT #13	2023-06-23 10:13
---------	------------------

MOT test number	925173315011
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-06-23
------------------	------------

- Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice

Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice

Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Minor

Nearside Upper Windscreen damaged but not adversely affecting driver's view Stone chip (3.2 (a) (i))
- Advice

Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice

Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #12**

2023-06-20 10:29

MOT test number

213691874238

Result**✗ Failed**

- Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- MAJOR** Offside Front Service brake excessively fluctuating (1.2.1 (e))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Minor** Nearside Upper Windscreen damaged but not adversely affecting driver's view Stone chip (3.2 (a) (i))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- MAJOR** Nearside Front Service brake excessively fluctuating (1.2.1 (e))

MOT #11

2022-06-11 08:05

MOT test number

214289923305

Result**✓ Passed**

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #10

2022-06-06 13:09

MOT test number

503068886240

Result**✗ Failed**

MAJOR Exhaust hydrocarbon content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MAJOR Fuel cap/sealing device ineffective (6.1.3 (b) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #9** 2021-06-24 17:33**MOT test number** 733775934844**Result** ✓ Passed**Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Both side under sill cover fitted**MOT #8** 2020-03-27 09:56**MOT test number** 691445459933**Result** ✗ Failed**DANGEROUS** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MAJOR** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))**MAJOR** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 195/55/16 (5.2.3 (d) (i))**DANGEROUS** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**MAJOR** Exhaust hydrocarbon content after 2nd fast idle exceeds default limits (8.2.1.2 (b))**MOT #7** 2019-01-15 10:53**MOT test number** 841260008812**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #6** 2017-12-14 13:06**MOT test number** 839810236404**Result** ✓ Passed**Advice** Under-trays fitted.**Advice** Items removed from driver's view prior to test

**MOT #5** 2017-01-05 12:26**MOT test number** 998736383198**Result** ✓ Passed**Advice** Coolant leak**MOT #4** 2016-01-05 11:46**MOT test number** 954875328634**Result** ✓ Passed**Advice** Undertrays fitted**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2015-01-12 16:19**MOT test number** 455682115085**Result** ✓ Passed**MOT #2** 2014-01-07 12:58**MOT test number** 171718102260**Result** ✓ Passed**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #1** 2012-12-03 11:14**MOT test number** 795258632344**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
23 June 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	23 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-12-29
Last registration	2023-06-23
Complete history	See info



Registration #1	2009-12-29	7 mi
Registration #2	2012-12-03	16.907 mi
Registration #3	2014-01-07	24.131 mi
Registration #4	2015-01-12	30.866 mi
Registration #5	2016-01-05	34.333 mi
Registration #6	2017-01-05	41.063 mi
Registration #7	2017-12-14	48.780 mi
Registration #8	2019-01-15	55.066 mi
Registration #9	2020-06-23	61.333 mi
Registration #10	2021-06-23	67.600 mi
Registration #11	2022-06-23	73.867 mi
Registration #12	2023-06-23	80.133 mi
Registration #13	2024-03-29	86.400 mi
Registration #14	2024-03-29	92.667 mi
Registration #15	2024-03-29	98.933 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1140 kg
Max. allowed weight	1515 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Engine number	A712I352
---------------	----------