



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BEETLE LUNA 8V
Colour	Blue
Year of manufacture	2007
Top speed	111 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	147 Nm at 3.800 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.7 mpg
Consumption extra urban	46.3 mpg
Consumption combined	36.2 mpg
CO2 emission	185 g/km
CO2 label	I





Internet history

Entry 1

Date	2022-06-18
Pictures	12
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://cargurus.co.uk)



MOT history

MOT expiry date	2024-07-14
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	16
Total items failed	7

MOT #18	2023-07-15 10:56
MOT test number	287799167080
Result	✓ Passed
Next expiry date	2024-07-14

MOT #17	2022-06-15 12:11
MOT test number	181980277021
Result	✓ Passed

MOT #16	2021-07-12 15:16
MOT test number	168108806208
Result	✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Minor	Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Minor	Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**MOT #15** 2020-02-24 10:47**MOT test number** 910487146619**Result** ✓ Passed**Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #14** 2019-03-19 16:32**MOT test number** 648357346257**Result** ✓ Passed**MOT #13** 2018-03-08 16:33**MOT test number** 806356724913**Result** ✓ Passed**Advice** Offside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #12** 2017-02-21 11:28**MOT test number** 302764460923**Result** ✓ Passed**MOT #11** 2017-02-21 11:28**MOT test number** 216695251739**Result** ✗ Failed**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)

**MOT #10** 2016-03-20 09:26**MOT test number** 363056996388**Result** ✓ Passed**MOT #9** 2016-03-19 12:28**MOT test number** 938748016617**Result** ✗ Failed**Fail** Nearside Front Headlamp not working on dipped beam (1.7.5a)**Fail** Offside Front Inner Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Front Inner Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #8** 2015-03-17 12:34**MOT test number** 177626475414**Result** ✓ Passed**Advice** Offside Rear Road wheel slightly damaged (4.2.A.1a)**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #7** 2014-02-27 15:35**MOT test number** 259388554018**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2014-02-27 10:37**MOT test number** 566908454094**Result** ✗ Failed**Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2013-03-01 10:45**MOT test number** 767090963050**Result** ✓ Passed**MOT #4** 2012-02-27 10:57**MOT test number** 806428352028**Result** ✓ Passed**MOT #3** 2011-03-02 10:44**MOT test number** 229901561007**Result** ✓ Passed**MOT #2** 2010-02-19 10:56**MOT test number** 950810150067**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #1** 2010-02-19 10:56**MOT test number** 983040250001**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
14 July 2024

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	33
<b>MOT expiry date</b>	14 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>PE07EPX</b>
Plate since	2024-03-29
Current registration	 <b>PE07EPX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-03-01
Last registration	2023-07-15
Complete history	<a href="#">See info</a>



Registration #1	2007-03-01	19 mi
Registration #2	2010-02-19	12.727 mi
Registration #3	2011-03-02	16.922 mi
Registration #4	2012-02-27	20.915 mi
Registration #5	2013-03-01	26.345 mi
Registration #6	2014-02-27	31.896 mi
Registration #7	2014-02-27	31.897 mi
Registration #8	2015-03-17	36.463 mi
Registration #9	2016-03-19	42.610 mi
Registration #10	2016-03-20	42.610 mi
Registration #11	2016-03-20	42.610 mi
Registration #12	2016-03-20	42.610 mi
Registration #13	2016-03-20	42.610 mi
Registration #14	2016-03-20	42.610 mi
Registration #15	2016-03-20	42.610 mi
Registration #16	2016-03-20	42.610 mi
Registration #17	2016-03-20	42.610 mi
Registration #18	2016-03-20	42.610 mi
Registration #19	2016-03-20	42.610 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1502 mm
Length	4081 mm
Wheel base	2516 mm
Kerb weight	1393 kg
Max. allowed weight	1770 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2

Number of seats	4
Number of axles	2
Engine number	BFS 062004