





General information

Make	ΤΟΥΟΤΑ
Model	COROLLA VVTI T SPIRIT
Colour	Grey
Year of manufacture	2005
Top speed	109 mph
0 - 60 mph	11.8 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	109 BHP
Max. torque	150 Nm at 3.800 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.6 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.7 mpg
CO2 emission	190 g/km
CO2 label	J







Internet history

Entry 1

Date

2021-10-21

Pictures

Listing price

4 <u>View report</u>







source: autotrader.co.uk



MOT history

MOT expiry date	2024-04-15
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	39
Total items failed	5

MOT #21		2023-03-31 15:44
MOT test	number	823370936834
Result		✓ Passed
Next exp	iry date	2024-04-15
Advice	Nearside Rear Nail in tyre	
Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))		
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	





MOT #20		2023-03-30 17:46
MOT test	number	599636412636
Result		🗙 Failed
MAJOR	Front Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
MAJOR	Front Headlamp lens seriously defective Both (4.1.1 (b) (ii))	
Advice	Nearside Rear Nail in tyre	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources	(4.7.1 (b) (i))

 MOT #19
 2022-04-04 14:39

 MOT test number
 769586698303

 Result
 ✓ Passed

 Advice
 Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #18	2021-04-13 13:51
MOT test number	195186950901
Result	✓ Passed
Advice Rear Tyre slightly damaged/cracking or perishing Bo	oth (5.2.3 (d) (ii))
Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Rear Brake disc worn, pitted or scored, but not serie	pusly weakened (1.1.14 (a) (ii))





MOT #17		2021-04-13 13:51	
MOT test number		670497119590	
Result		🗙 Failed	
Advice Rear Brake disc	Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice Rear Tyre slightly damaged/cracking or perishing Both (5.2.3 (d) (ii))			
Pass with rectification Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))			
Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))			
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))			
Pass with rectification	Nearside Headlamp aim projected beam image is o	obviously incorrect (4.1.2 (c))	
Pass with rectification	Central Stop lamp(s) not working (4.3.1 (a) (ii))		

MOT #16	2020-04-16 16:00
MOT test number	797278194176
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
MOT #15	2019-10-04 12:55
MOT test number	294221304089

🗸 Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge worn inner and outer edges (5.2.3 (e))

Result



WK55	TYC
report date:	2024-03-28

MOT #14		2019-10-04 09:50
MOT test	number	848728605592
Result		🗙 Failed
MAJOR	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))	
Advice	Advice Nearside Front Tyre worn close to legal limit/worn on edge worn inner and outer edges (5.2.3 (e))	
MAJOR Nearside Rear Parking brake inoperative on one side (1.4.1 (a))		
DANGER	OUS Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

MOT #13	2018-10-05 07:45
MOT test number	286444308878
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #12		2018-10-05 07:45
MOT test number		857812793565
Result		🗙 Failed
Pass with rectification	Brake lever has insufficient reserve travel (1.1.2 (a))	
Advice Offside Front Ty	re worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #11	2017-10-12 16:50
MOT test number	935591744054
Result	✓ Passed





MOT #10		2016-08-18 09:00
MOT test	number	676624104239
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit outer edge worn low (4.1.E.1)	
Advice	Rear suspension heavily corroded	
Advice	Offside Front nail in tyre	

MOT #9		2015-08-11 16:08
MOT test	number	357673525283
Result		✓ Passed
Advice	Offside Rear Shock absorber has slight corrosion to the casing (2.7.2a)	
Advice	Nearside Rear Shock absorber has slight corrosion to the casing (2.7.2a)	
Advice	Parking brake lever has little reserve travel (3.1.6b)	

МОТ #8	2014-08-11 15:46
MOT test number	339093124433
Result	✓ Passed
Notice Rear axle bushes perishing.	

MOT #7	2013-08-12 14:45
MOT test number	489224823233
Result	✓ Passed
MOT #6	2012 00 15 16.24

MOT #6	2012-08-15 16:24
MOT test number	266568322228
Result	✓ Passed





MOT #5	2012-08-14 16:11
MOT test number	315147122453
Result	🗙 Failed
Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach a (4.1.D.1a) Notice O/s/r tyre in poor condition	the ply or cords
MOT #4	2011-08-18 16:19
MOT test number	369440531252
Result	🗸 Passed
MOT #3	2010-08-23 12:39
MOT test number	371865030247
Result	✓ Passed
MOT #2	2009-08-10 14:44
MOT test number	610912229235
Result	✓ Passed
MOT #1	2008-08-26 15:36
MOT test number	293329438270
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (3.5.1g)	



Tax & MOT check

✓ Taxed Tax due: 1 October 2024	X MOT Expired: 15 April 2024
Tax status	Valid until 1 October
Days left	155
MOT expiry date	15 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	Lamp
Туре	
Damage 2	AMPLI
Damage 2	E E H - S - A
Date	*
Category	AMP.
Туре	

Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-09-01
Last registration	2023-03-31
Complete history	See info



Registration #1	2005-09-01	17 mi
Registration #2	2008-08-26	18.434 mi
Registration #3	2009-08-10	22.933 mi
Registration #4	2010-08-23	27.860 mi
Registration #5	2011-08-18	32.944 mi
Registration #6	2012-08-14	38.407 mi
Registration #7	2012-08-15	38.414 mi
Registration #8	2013-08-12	43.631 mi
Registration #9	2014-08-11	48.152 mi
Registration #10	2015-08-11	52.499 mi
Registration #11	2016-08-18	55.980 mi
Registration #12	2017-10-12	57.020 mi
Registration #13		11.117 esi
Registration #14		11.112 esi
Registration #15		11.222 esi
Registration #16		11.777 est
Registration #17		11.777 esi
Registration #18		11.777 est
Registration #19		11.222 esi
Registration #20		11.117 est
Registration #21		11.117 esi
Registration #22		11.117 est
Registration #23		11.777 esi

More info >





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1255 kg
Max. allowed weight	1670 kg
Additional information	
Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 15/15

Number of axles	2
Engine number	3ZZU625053