






report date: 2024-03-29

General information

Make	RENAULT
Model	TRAFIC LL29 BUSINESS ENERGY DCI
Colour	White
Year of manufacture	2016
Top speed	105 mph
0 - 60 mph	11.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	320 Nm at 1.500 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	53.3 mpg
Consumption combined	49.6 mpg
CO2 emission	145 g/km
CO2 label	F



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date 2021-12-21

Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

N/I	α		uc:	t۸	r\/
101	•		115	w	ıv
	•	Γh			. ,

MOT expiry date	2025-01-24
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	26
Total items failed	7

MOT #9	2024-01-13 11:39
MOT test number	704931785215
Result	✓ Passed
Next expiry date	2025-01-24

MOT #8	2023-01-12 13:25
MOT test number	310664575553
Result	✓ Passed
Advice Chip in windscreen	

MOT #7		2022-01-25 09:58
MOT test	number	294111605683
Result		✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Chips in screen	
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	

CarCheck.co.uk page 3/13



report date: 2024-03-29



MOT #5		2021-08-23 11:37
MOT test	number	281971694959
Result		✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Rear tyres slight misshaping	
Advice	Central Rear Seat belt webbing slightly damaged or frayed near side (7.1.2 (b) (ii))

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #4 2021-08-20 12:05

MOT test number 574595992524

Result X Failed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened scored (1.1.14 (a) (ii))

Fail Front Brakes imbalanced across an axle (1.2.1 (b) (i))

Advice Rear tyres slight misshaping

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Advice Central Rear Seat belt webbing slightly damaged or frayed near side (7.1.2 (b) (ii))

Fail Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #3 2020-08-20 08:11

MOT test number 749178035512

Result \rightarrow Passed

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))

Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT test number

Result

Advice Offside Seat belt slightly damaged 2nd row (7.1.2 (b) (i))

Advice Nearside Seat belt slightly damaged 2nd row (7.1.2 (b) (i))

MOT #1

MOT test number

Fesult

Advice Nearside Seat belt slightly damaged second row (7.1.2 (b) (i))

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	24 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

<u> </u>	والمستحدث والمالية
Owner	nistorv
OWITCE	ilistoi y

For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is		AULT

	More info	>
Plate changes		
See in this check if this RENAULT had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-04-20
Last registration	2024-01-13
Complete history	See info



Registration #1	2016-04-20	24 mi
Registration #2	2018-09-19	33.460 mi
Registration #3	2019-09-06	75.472 mi
Registration #4	2020-08-20	112.044 mi
Registration #5	2021-08-20	156.447 mi
Registration #6	2021-08-23	156.452 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		D.777 es
Registration #11		11.777 mg

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

S0225	Air conditionin
S0295	
50482	
50501	
60566	
60567	
60569	

Safety ratings

NCAP rating	***
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	see crash video



Dimensions & weight

Width	2283 mm
Height	1971 mm
Length	5399 mm
Kerb weight	1923 kg
Max. allowed weight	3020 kg

Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	9
Number of axles CarCheck.co.uk	2 page 13/13

Engine number

C039849