



report date: 2024-03-28

General information

Make	VAUXHALL
Model	TIGRA SXI AC 16V
Colour	Black
Year of manufacture	2009
Top speed	107 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	125 Nm at 4.000 rpm
Engine capacity	1.364 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	56.5 mpg
Consumption combined	46.3 mpg
CO2 emission	146 g/km
CO2 label	F





Internet history

Entry 1

Date	2022-01-18
Pictures	9
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-02-27
MOT pass rate	62 %
MOT passed	13
Failed MOT tests	8
Total advice items	34
Total items failed	20

MOT #21	2024-02-28 10:44
MOT test number	276641149325
Result	✓ Passed
Next expiry date	2025-02-27
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Play in steering rack inner joint(s)
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Surface corrosion to front subframe
Advice	Rear Coil spring corroded both (5.3.1 (b) (i))

**MOT #20**

2024-02-26 11:12

MOT test number

207414360397

Result**✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))
- Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))
- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Surface corrosion to front subframe
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Coil spring corroded both (5.3.1 (b) (i))
- Fail** Offside Parking brake inoperative on one side (1.4.1 (a))
- Advice** Play in steering rack inner joint(s)
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Fail** Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

MOT #19

2023-02-20 13:21

MOT test number

966164229931

Result**✓ Passed**

- Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Slight blow on center exhaust.
- Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #18** 2023-02-15 10:39**MOT test number** 891188457780**Result** ✗ Failed**Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Slight blow on center exhaust.**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Rear number plate light not working**Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**MOT #17** 2022-02-17 13:02**MOT test number** 443970188152**Result** ✓ Passed**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #16** 2022-01-27 14:22**MOT test number** 344973376077**Result** ✗ Failed**Fail** Emissions not tested (8.2.1.2 (d))**Fail** Rear Exhaust silencer insecure (8.1.1 (b) (i))**Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

**MOT #15** 2021-01-20 12:51**MOT test number** 712956442415**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #14** 2021-01-20 11:05**MOT test number** 573297681419**Result** ✗ Failed**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #13** 2020-01-27 14:56**MOT test number** 551028782376**Result** ✓ Passed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #12** 2019-02-11 15:24**MOT test number** 283228836570**Result** ✓ Passed**MOT #11** 2018-03-02 09:00**MOT test number** 483868333059**Result** ✓ Passed

**MOT #10** 2017-02-21 15:55**MOT test number** 393255764259**Result** ✓ Passed**MOT #9** 2017-02-21 09:19**MOT test number** 136723562915**Result** ✗ Failed**Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Offside rear brake binding (3.7.B.1)**MOT #8** 2016-03-07 15:48**MOT test number** 685145039968**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit INNER EDGE (4.1.E.1)**MOT #7** 2015-03-16 14:26**MOT test number** 669295375002**Result** ✓ Passed**MOT #6** 2015-03-16 13:41**MOT test number** 615085275054**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #5** 2014-03-12 14:27**MOT test number** 938321374088**Result** ✓ Passed**MOT #4** 2013-03-04 13:14**MOT test number** 189243463422**Result** ✓ Passed**MOT #3** 2013-03-04 09:33**MOT test number** 557443863078**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #2** 2012-03-19 10:15**MOT test number** 719069972075**Result** ✓ Passed**MOT #1** 2012-03-19 10:15**MOT test number** 157259272046**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (1.8)



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
27 February 2025

Tax status	Valid until 1 October
Days left	155
MOT expiry date	27 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Number of owners	1
Current owner since	2019-09-29
Previous owner since	2019-09-29
Number of owners	1
Current owner since	2019-09-29
Previous owner since	2019-09-29

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 E009ZGB
Plate since	2019-09-29
Current registration	 E009ZGB
Plate since	2019-09-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2009-03-31
Last registration	2024-02-28
Complete history	See info



Registration #1	2009-03-31	16 mi
Registration #2	2012-03-19	26.922 mi
Registration #3	2013-03-04	34.978 mi
Registration #4	2013-03-04	34.978 mi
Registration #5	2014-03-12	42.971 mi
Registration #6	2015-03-16	53.058 mi
Registration #7	2015-03-16	53.058 mi
Registration #8	2016-03-07	63.228 mi
Registration #9	2017-02-21	72.536 mi
Registration #10	2017-02-21	72.536 mi
Registration #11	2018-03-02	83.503 mi
Registration #12	2019-03-20	95.557 mi
Registration #13	2019-03-20	95.557 mi
Registration #14	2019-03-20	95.557 mi
Registration #15	2019-03-20	95.557 mi
Registration #16	2019-03-20	95.557 mi
Registration #17	2019-03-20	95.557 mi
Registration #18	2019-03-20	95.557 mi
Registration #19	2019-03-20	95.557 mi
Registration #20	2019-03-20	95.557 mi
Registration #21	2019-03-20	95.557 mi
Registration #22	2024-02-28	95.557 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1707 mm
Height	1494 mm
Length	3999 mm
Wheel base	2511 mm
Kerb weight	1102 kg
Max. allowed weight	1615 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	19SC2680