





report date: 2024-03-28

#### General information

Make	BMW
Model	740 430D M SPORT GRAN COUPE
Colour	Grey
Year of manufacture	2017
Top speed	155 mph
0 - 60 mph	5.6 seconds
Gearbox	8 speed automatic

## Engine & fuel consumption

Power	255 BHP
Max. torque	560 Nm at 1.500 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	58.9 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/11



## Internet history

#### Entry 1

Date 2021-01-29

Pictures 4

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2025-03-06
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	7
Total items failed	0

MOT #6	2024-03-07 14:15
MOT test number	462086867113
Result	✓ Passed
Next expiry date	2025-03-06
Advice Nearside Rear tyre worn to limit	

MOT #5	2023-03-06 15:43
MOT test number	625854493110
Result	✓ Passed
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #4		2022-02-08 13:26
MOT test	number	828076489785
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Prop shaft flexible coupling slightly deteriorated (6.1.7 (d) (i))	

MOT #3	2021-02-06 10:10
MOT test number	403751463494
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/11



MOT #2 2020-02-07 16:09

**MOT test number** 256964475817

**Result** ✓ Passed

**MOT #1** 2020-02-06 11:45

MOT test number 501363634777

**Result** X Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge bald on edge (advise rep) (5.2.3 (e))

**DANGEROUS** Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

CarCheck.co.uk page 4/11



## Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	6 March 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 5/11



#### Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



#### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



## Owner history

For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report \( \frac{1}{2} \)	
***************************************	
	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

#### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-03-01
Last registration	2024-03-07
Complete history	See info



Registration #1	2017-03-01	26 mi
Registration #2	2020-02-06	32.203 mi
Registration #3	2020-02-07	32.203 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 10/11



## Car features

S0225	Air conditioning
S0295	
S0482	
50501	
S0566	
S0567	
50569	

## Safety ratings

NCAP rating	****
Adult	95%
Children	84%
Pedestrian	78%
Safety systems	86%
Overall rating	89%
Video	see crash video



## Dimensions & weight

Width	1825 mm
Height	1397 mm
Length	4640 mm
Wheel base	2810 mm
Kerb weight	1605 kg
Max. allowed weight	2175 kg

# Additional information

Fuel tank capacity	57 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats CarCheck.co.uk	5 page 11/:

Number of axles2Engine number71305043