



SA67DUJ

report date: 2024-03-29

General information

Make	MINI
Model	CLUBMAN COOPER
Colour	Blue
Year of manufacture	2017
Top speed	129 mph
0 - 60 mph	8.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	220 Nm at 4.200 rpm
Engine capacity	1.499 cc
Cylinders	3
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	62.8 mpg
Consumption combined	54.3 mpg
CO2 emission	118 g/km
CO2 label	C



**Internet history****Entry 7**

Date	2021-11-27
Pictures	10
Listing price	View report

**source: autoonline.co.uk****Entry 6**

Date	2021-11-18
Pictures	0
Listing price	View report

source: heycar.co.uk**Entry 5**




Date	2021-11-06
Pictures	0
Listing price	View report

source: autotrader.co.uk**Entry 4**

Date	2021-11-05
Pictures	0
Listing price	View report

source: cargurus.co.uk**Entry 3**

Date	2021-08-15
Pictures	15
Listing price	View report




source: [heycar.co.uk](https://www.heycar.co.uk)

Entry 2	
Date	2021-07-07
Pictures	0
Listing price	View report

source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1	
Date	2021-01-22
Pictures	31
Listing price	View report



source: [yesauto.com](https://www.yesauto.com)



MOT history

MOT expiry date	2024-07-20
MOT pass rate	100 %
MOT passed	4
Failed MOT tests	0
Total advice items	8
Total items failed	0

MOT #4 2023-06-27 10:53

MOT test number 510350928885

Result ✓ Passed

Next expiry date 2024-07-20

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2022-07-08 07:56

MOT test number 752337781137

Result ✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2 2021-07-21 16:34

MOT test number 342615905285

Result ✓ Passed



MOT #1	2020-10-05 11:50
MOT test number	637732170356
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
20 July 2024

Tax status	Valid until 1 December
Days left	215
MOT expiry date	20 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	SA67DUJ
Plate since	2019-03-29
Current registration	SA67DUJ
Plate since	2019-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2017-09-29
Last registration	2023-06-27
Complete history	See info



Registration #1	2017-09-29	17 mi
Registration #2	2020-10-05	25.102 mi
Registration #3	2019-09-29	25.277 mi
Registration #4	2019-09-29	25.277 mi
Registration #5	2021-07-21	28.907 mi
Registration #6	2019-09-29	25.277 mi
Registration #7	2019-09-29	25.277 mi
Registration #8	2019-09-29	25.277 mi
Registration #9	2019-09-29	25.277 mi
Registration #10	2019-09-29	25.277 mi
Registration #11	2019-09-29	25.277 mi
Registration #12	2019-09-29	25.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	79%
Children	73%
Pedestrian	66%
Safety systems	56%
Overall rating	71%
Video	see crash video



Dimensions & weight

Width	1932 mm
Height	1415 mm
Length	3821 mm
Wheel base	2495 mm
Kerb weight	1280 kg
Max. allowed weight	1670 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Engine number	35849848
---------------	----------