



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO S
Colour	Silver
Year of manufacture	2010
Top speed	98 mph
0 - 60 mph	16.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	59 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	51.4 mpg
CO2 emission	128 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-06-19
Pictures	14
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-29
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	22
Total items failed	0

MOT #13	2023-10-09 10:21
MOT test number	964687814432
Result	✓ Passed
Next expiry date	2024-10-29
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #12	2022-10-17 16:07
MOT test number	660099518491
Result	✓ Passed
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Tyre slightly damaged/cracking or perishing both front (5.2.3 (d) (ii))

**MOT #11**

2022-10-17 10:21

MOT test number

985451075462

Result**✗ Failed**

- MAJOR** Suspension arm pin or bush excessively worn both front wish bone rear bushes (5.3.4 (a) (i))
- MAJOR** Headlamp aim too high both (4.1.2 (a))
- Advice** Tyre slightly damaged/cracking or perishing both front (5.2.3 (d) (ii))
- MAJOR** Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- MAJOR** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- MAJOR** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #10

2021-10-22 09:16

MOT test number

850951474133

Result**✓ Passed****MOT #9**

2020-10-30 16:53

MOT test number

774237124814

Result**✓ Passed**

**MOT #8** 2020-10-24 13:36**MOT test number** 952247565173**Result** ✗ Failed

MAJOR Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MAJOR Offside Front Outer Seat belt anchorage prescribed area strength or continuity significantly reduced sill (7.1.1 (a) (i))

MAJOR Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MAJOR Exhaust has a major leak of exhaust gases (6.1.2 (a))

MOT #7 2019-03-11 14:41**MOT test number** 863129817630**Result** ✓ Passed**MOT #6** 2018-02-16 16:14**MOT test number** 810325668401**Result** ✓ Passed**MOT #5** 2017-02-16 15:52**MOT test number** 990340522806**Result** ✓ Passed**MOT #4** 2016-02-13 13:25**MOT test number** 452962016409**Result** ✓ Passed



MOT #3	2015-02-18 15:59
MOT test number	849169945056
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Notice	Both rear tyres cracking

MOT #2	2014-02-19 17:48
MOT test number	438430454038
Result	✓ Passed

MOT #1	2013-02-23 09:07
MOT test number	166704753470
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
29 October 2024

Tax status	Valid until 1 June
Days left	34
MOT expiry date	29 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 YK10ZJX
Plate since	2019-06-29
Current registration	 YK10ZJX
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-03-01
Last registration	2023-10-09
Complete history	See info



Registration #1	2010-03-01	11 mi
Registration #2	2013-02-23	24.367 mi
Registration #3	2014-02-19	34.324 mi
Registration #4	2015-02-18	43.527 mi
Registration #5	2016-02-13	52.863 mi
Registration #6	2017-02-16	62.847 mi
Registration #7	2018-02-16	72.654 mi
Registration #8	2019-03-11	79.807 mi
Registration #9	2020-03-20	85.377 mi
Registration #10	2021-03-20	91.377 mi
Registration #11	2022-03-20	97.377 mi
Registration #12	2023-03-20	103.377 mi
Registration #13	2024-03-20	109.377 mi
Registration #14	2025-03-20	115.377 mi
Registration #15	2026-03-20	121.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1682 mm
Height	1462 mm
Length	3970 mm
Wheel base	2470 mm
Kerb weight	1067 kg
Max. allowed weight	1550 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5

Number of seats	5
Engine number	CGP 038843