



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	COUPE SIII
Colour	Grey
Year of manufacture	2009
Top speed	129 mph
Gearbox	4 speed Manual

Engine & fuel consumption

Power	141 BHP
Max. torque	186 Nm at 4.500 rpm
Engine capacity	1.975 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.9 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.3 mpg
CO2 emission	193 g/km
CO2 label	J






Internet history

Entry 2

Date	2024-02-24
Pictures	9
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)

Entry 1

Date	2022-01-25
Pictures	9
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-02-25
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	45
Total items failed	10

MOT #16	2024-02-26 19:04
MOT test number	259836854451
Result	✓ Passed
Next expiry date	2025-02-25
Advice	Underbody heavily covered in underseal

**MOT #15**

2023-03-30 13:20

**MOT test number**

405087282202

**Result**

✓ Passed

- Advice** Fuel Pipe/s corroded
- Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Rear Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Power steering component has slight seepage from a component (2.1.5 (a))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Supplementary restraint system warning lamp does not illuminate (7.1.6 (a))

**MOT #14**

2023-03-28 11:17

**MOT test number**

302914840814

**Result****✗ Failed****Fail** Nearside Rear Brake pad(s) contaminated (1.1.13 (b))**Advice** Offside Rear Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Power steering component has slight seepage from a component (2.1.5 (a))**Fail** Offside Steering rack gaiter missing or no longer prevents the ingress of dirt split (2.1.3 (g) (ii))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Nearside Rear Hydraulic brake calliper leaking and braking performance affected (1.1.16 (b) (ii))**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Fuel Pipe/s corroded**Fail** Nearside Rear Brake disc contaminated (1.1.14 (b))**Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Fail** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))**Advice** Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))**Minor** Brake hydraulic reservoir fluid level below minimum level (1.1.10 (d) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Supplementary restraint system warning lamp does not illuminate (7.1.6 (a))**Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))**Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #13** 2022-02-08 12:31**MOT test number** 429433026258**Result** ✓ Passed**MOT #12** 2021-01-23 13:16**MOT test number** 885107088322**Result** ✓ Passed**Advice** Exhaust system corroded and deteriorated**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))**Advice** Reverse lamp inoperative**MOT #11** 2021-01-23 11:40**MOT test number** 130802478746**Result** ✗ Failed**Fail** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Fail** Offside Rear Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))**Advice** Exhaust system corroded and deteriorated**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))**Advice** Reverse lamp inoperative

**MOT #10**

2020-02-15 08:56

**MOT test number**

948842093874

**Result**

✓ Passed

- Advice** Exhaust mid section to rear silencer flange corroded
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Advice** Rear Brake pipe corroded, covered in grease or other material n/s and o/s (1.1.11 (c))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened n/s and o/s lipped (1.1.14 (a) (ii))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #9**

2019-02-06 12:29

**MOT test number**

843052444996

**Result**

✓ Passed

- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear exhaust corroded

**MOT #8**

2018-02-08 10:53

**MOT test number**

339286455843

**Result**

✓ Passed

**MOT #7**

2017-02-16 14:46

**MOT test number**

123818067471

**Result**

✓ Passed

**MOT #6** 2016-02-11 14:51**MOT test number** 991299526086**Result** ✓ Passed**MOT #5** 2015-02-10 15:04**MOT test number** 237481945029**Result** ✓ Passed**MOT #4** 2015-02-03 12:32**MOT test number** 528994835016**Result** ✗ Failed**Fail** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #3** 2014-02-19 13:37**MOT test number** 147940154421**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2013-02-22 11:36**MOT test number** 885833653029**Result** ✓ Passed**Notice** Noise from nearside rear wheel bearing**MOT #1** 2012-01-23 11:14**MOT test number** 459823622007**Result** ✓ Passed**Notice** Slight damage to nearside front tyre outer wall





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
25 February 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	307
<b>MOT expiry date</b>	25 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	J
<b>Single payment (12 months)</b>	£ 365,00,-
<b>Single six month payment</b>	£ 200,75,-
<b>Total payable by 12 monthly instalments</b>	£ 383,25,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	<b>DK09UOD</b>
Plate since	2019-03-28
Current registration	<b>DK09UOD</b>
Plate since	2019-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-03-11
Last registration	2024-02-26
Complete history	<a href="#">See info</a>



Registration #1	2009-03-11	14 mi
Registration #2	2012-01-23	13.622 mi
Registration #3	2013-02-22	14.724 mi
Registration #4	2014-02-19	19.282 mi
Registration #5	2015-02-03	33.461 mi
Registration #6	2015-02-10	34.179 mi
Registration #7	2016-02-11	45.436 mi
Registration #8	2017-02-16	52.463 mi
Registration #9	2018-02-08	61.476 mi
Registration #10	2019-02-06	66.543 mi
Registration #11	2020-02-02	71.577 mi
Registration #12	2021-02-02	76.577 mi
Registration #13	2022-02-02	81.577 mi
Registration #14	2023-02-02	86.577 mi
Registration #15	2024-02-02	91.577 mi
Registration #16	2025-02-02	96.577 mi
Registration #17	2026-02-02	101.577 mi
Registration #18	2027-02-02	106.577 mi
Registration #19	2028-02-02	111.577 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1760 mm
Height	1330 mm
Length	4395 mm
Wheel base	2530 mm
Kerb weight	1342 kg
Max. allowed weight	1740 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	G4GC8222963