





report date: 2024-03-29

General information

Make	CITROEN
Model	DS3 E-HDI DSTYLE
Colour	Grey
Year of manufacture	2015
Top speed	113 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	85.6 mpg
Consumption combined	76.4 mpg
CO2 emission	95 g/km
CO2 label	A



CarCheck.co.uk page 1/12



Internet history

Entry 2

Date 2021-10-27

Pictures 8

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-10-27
------	------------


Pictures 8

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-11-04
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	17
Total items failed	6

MOT #9		2023-10-27 14:09
MOT test	number	721083380277
Result		✓ Passed
Next expi	ry date	2024-11-04
Advice	Offside Front Track rod end ball joint has slight play Just acceptable (2.1.3 (b) (i))	
Advice	Advise Grease around both front CV Gaiters but found no leaks	

MOT #8		2022-11-01 17:44
MOT test	number	359399228127
Result		✓ Passed
Advice	Rear subframe surface corrosion	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #7		2022-10-29 15:10
MOT test	number	676593087407
Result		× Failed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Rear subframe surface corrosion		
Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))		

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #6 2021-11-05 15:45

MOT test number 822413055206

MOT #5 2021-03-11 13:36

MOT test number 232446295690

Result Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Exhaust mounting defective (6.1.2 (a))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4 2021-03-11 13:36

MOT test number 355181075359

Result X Failed

Pass with rectification Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Pass with rectification Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Pass with rectification Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Rear Exhaust mounting defective (6.1.2 (a))

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #3		2020-03-18 10:48
MOT test	number	617988324028
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Inner Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Rear Exhaust mounting defective (6.1.2 (a))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #2	2019-03-20 10:51
MOT test number	923114954345
Result	✓ Passed
MOT #1	2018-03-21 12:44
MOT test number	153139995274
Result	✓ Passed
Advice Rear discs showing corrosion but meet efficiency	

CarCheck.co.uk page 5/12



Tax & MOT check





Expires: 4 November 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	4 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12




report date: 2024-03-29

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

CX15WDD

report date: 2024-03-29

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report here.

Plate changes

More info >

More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-03-30
Last registration	2023-10-27
Complete history	See info



Registration #1	2015-03-30	14 mi
Registration #2	2018-03-21	45.890 mi
Registration #3	2019-03-20	53.184 mi
Registration #4	2020-03-18	60.038 mi
Registration #5	2021-03-11	63.412 mi
Registration #6	2021-03-11	63.412 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es

More info >

CarCheck.co.uk page 11/12



Safety ratings

NCAP rating	****
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1728 mm
Height	1524 mm
Length	3941 mm
Wheel base	2464 mm
Kerb weight	1085 kg
Max. allowed weight	1602 kg

Additional information

Fuel tank capacity	48 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBFM0107961

CarCheck.co.uk page 12/12