





### General information

Make	NISSAN
Model	PATHFINDER DCI TEKNA
Colour	Black
Year of manufacture	2011
Top speed	115 mph
0 - 60 mph	11.0 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	188 BHP
Power	100 BHP
Max. torque	450 Nm at 2.000 rpm
Engine capacity	2.488 сс
Cylinders	4
Fuel type	Diesel
Consumption city	26.2 mpg
Consumption extra urban	39.2 mpg
Consumption combined	33.2 mpg
CO2 emission	224 g/km
CO2 label	К







Internet history	
Entry 2	
Date	2021-11-06
Pictures	0
Listing price	View report
source: cargurus.co.uk	
Entry 1	
Date	2021-11-04
Pictures	0
Listing price	View report

source: autotrader.co.uk



## MOT history

MOT expiry date	2024-11-06
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	18
Total items failed	2

MOT #13	2023-11-07 11:06
MOT test number	911624581359
Result	✓ Passed
Next expiry date	2024-11-06

MOT #12		202	3-11-04 08:59
MOT test I	number	1	70295729578
Result			🗙 Failed
MAJOR	Nearside Front T	rack rod end ball joint has excessive play (2.1.3 (b) (i))	
Pass wit	h rectification	Offside Front Headlamp not working on main beam (4.1.1 (a) (ii))	
MAJOR Central Brake lever has insufficient reserve travel (1.1.2 (a))			
Pass wit	h rectification	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	

MOT #11	2023-01-23 13:50
MOT test number	248670133770
Result	✓ Passed
<b>Minor</b> Offside Rear Registration plate lamp inoperative in the case of mu (4.7.1 (b) (i))	Iltiple lamps or light sources





MOT #10		2023-01-21 08:48
MOT test	number	940491343328
Result		🗙 Failed
<b>Minor</b> (4.7.1 (b)	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or lig(i))	ght sources
MAJOR	Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
MAJOR	Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	
MAJOR	Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))	

МОТ #9	2022-01-14 14:52
MOT test number	944997998383
Result	✓ Passed
Advice General corrosion under vehicle	

MOT #8	2021-12-13 11:45
MOT test number	441433657012
Result	🗙 Failed
<b>MAJOR</b> Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
<b>MAJOR</b> Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Advice General surface corrosion under vehicle	

MOT #7	2021-01-12 16:25
MOT test number	579007346322
Result	✓ Passed
Advice O/s/f fog light broken	





MOT #6		2020-01-09 12:37
MOT test	number	906031462069
Result		✓ Passed
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	

MOT #5	2019-01-09 12:43
MOT test number	459114674599
Result	Passed
Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

МОТ #4	2018-01-17 09:15
MOT test number	305459479204
Result	✓ Passed

MOT #3	2017-01-21 09:51
MOT test number	443159061366
Result	✓ Passed

MOT #2	2015-02-16 12:42
MOT test number	587667345027
Result	✓ Passed

MOT #1		2014-02-05 14:06
MOT test	number	536196634005
Result		✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Under-trays fitted obscuring some underside components	



Tax & MOT check

✓ Taxed Tax due: 1 November 2024	✓ MOT Expires: 6 November 2024
Tax status	Valid until 1 November
Days left	187
MOT expiry date	6 November 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	К
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-





#### Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	E.S.
Туре	

#### Extra NISSAN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	
**********	
********	
*******	
***********	
********	
	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





#### Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 





## Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-02-19
Last registration	2023-11-07
Complete history	See info



Registration #1	2011-02-19	29 mi
Registration #2	2014-02-05	28.936 mi
Registration #3	2015-02-16	39.119 mi
Registration #4	2017-01-21	58.716 mi
Registration #5	2018-01-17	69.464 mi
Registration #6	2019-01-09	81.060 mi
Registration #7	2020-01-09	94.330 mi
Registration #8	2021-01-12	102.773 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		
negistration # 11		11.777 esi
Registration #12		10.000 est
		01.000 est 01.000 est 01.000 est
Registration #12		01.000 est 0.000 est 01.000 est 01.000 est
Registration #12 Registration #13		01.000 est 0.000 est 01.000 est 01.000 est 01.000 est

More info >





### Car features

S0225	Air conditioning
\$0295	
S0482	
S0501	
\$0566	
S0567	
S0569	

# Safety ratings

Number of seats CarCheck.co.uk

**NCAP** rating

Video

see crash video



Dimensions & weight	
Width	1848 mm
Height	1785 mm
Length	4813 mm
Wheel base	2853 mm
Kerb weight	2090 kg
Max. allowed weight	2880 kg
Additional information	
Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	5

7

Number of axles	2
Engine number	711479