



report date: 2024-03-29

General information

Make	LAND ROVER
Model	FREELANDER SD4 HSE LUXURY
Colour	Green
Year of manufacture	-
Top speed	118 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	190 BHP
Max. torque	420 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	32.5 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.4 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-24
Pictures	49
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT #6</b>	2021-01-11 08:42
<b>MOT test number</b>	165366223992
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-01-12
<b>Advice</b>	Offside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
<b>Advice</b>	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Advice</b>	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

<b>MOT #5</b>	2019-07-08 16:47
<b>MOT test number</b>	881365041002
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Minor</b>	Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

<b>MOT #4</b>	2018-07-09 13:41
<b>MOT test number</b>	176379836806
<b>Result</b>	✓ Passed

<b>MOT #3</b>	2017-07-13 07:34
<b>MOT test number</b>	858914683604
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
<b>Advice</b>	Nearside Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
<b>Advice</b>	Offside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2016-09-19 14:03
MOT test number	378366642393
Result	✓ Passed

MOT #1	2016-09-19 10:13
MOT test number	749962301410
Result	✗ Failed
Fail	Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
Fail	Offside Rear brake disc in such a condition that it is seriously weakened (3.5.1i)
Fail	Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
Fail	Nearside Rear brake disc in such a condition that it is seriously weakened (3.5.1i)



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	OY63XRK
Plate since	2019-09-29
Current registration	OY63XRK
Plate since	2019-09-29

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >





Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2013-10-14
Last registration	2021-01-11
Complete history	<a href="#">See info</a>



Registration #1	2013-10-14	20 mi
Registration #2	2016-09-19	56.452 mi
Registration #3	2016-09-19	56.452 mi
Registration #4	2017-07-13	74.570 mi
Registration #5	2019-05-29	75,377 mi
Registration #6	2019-05-29	75,377 mi
Registration #7	2019-05-29	75,377 mi
Registration #8	2019-05-29	75,377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2180 mm
Height	1740 mm
Length	4500 mm
Wheel base	2660 mm
Kerb weight	1770 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	DZ784152302224DT