



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 D DRIVE S
Colour	Silver
Year of manufacture	2009
Top speed	118 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	108 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	104 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-12-02
Pictures	11
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-29
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	33
Total items failed	9

MOT #17	2023-11-30 09:06
MOT test number	577502231147
Result	✓ Passed
Next expiry date	2024-11-29

MOT #16	2023-11-27 13:13
MOT test number	805594326952
Result	✗ Failed
Fail	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
Fail	Windscreen washer not working (3.5 (a))

MOT #15	2022-11-28 14:36
MOT test number	434358177033
Result	✓ Passed
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge should be monitored very worn but no to cords at time of test (5.2.3 (e))

**MOT #14**

2021-11-05 17:11

MOT test number

244508439171

Result

✓ Passed

Minor

Windscreen damaged but not adversely affecting driver's view Stonechip (3.2 (a) (i))

Advice

Fluid leak, but not excessive Possible exhaust additive fluid leak from tank (8.4.1 (a) (i))

Minor

Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

Advice

Rear Brake hose slightly deteriorated Both (1.1.12 (b) (ii))

MOT #13

2021-09-10 15:05

MOT test number

559855313446

Result

✗ Failed

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

Advice

Rear Tyre slightly damaged/cracking or perishing both slightly cracking and perishing (5.2.3 (d) (ii))

Fail

Nearside Front Lower Suspension arm pin or bush excessively worn bottom arm rear bush (5.3.4 (a) (i))

MOT #12

2020-07-30 15:30

MOT test number

485327303287

Result

✓ Passed

Advice

Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement toe adjustment arm (5.3.4 (a) (i))

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Offside Front Seat belt flexible stalk damaged (7.1.2 (b) (i))

**MOT #11**

2020-07-30 13:03

MOT test number

180987577141

Result**✗ Failed****Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Rear Service brake excessively fluctuating both rear`s (1.2.1 (e))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement toe adjustment arm (5.3.4 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Rear Brake performance not tested (1.2.1 (g))**Fail** Offside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))**Advice** Offside Front Seat belt flexible stalk damaged (7.1.2 (b) (i))**MOT #10**

2019-08-27 09:20

MOT test number

737647207276

Result**✓ Passed****Advice** Offside Front Seat belt flexible stalk damaged (7.1.2 (b) (i))**MOT #9**

2018-08-22 10:48

MOT test number

251193390407

Result**✓ Passed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Coolant low**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front orange marker lamp not working**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8** 2018-08-17 08:34**MOT test number** 300287751869**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Coolant low**Fail** Horn not working (7.7 (a) (ii))**Advice** Offside Front orange marker lamp not working**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Position lamp not working (4.2.1 (a))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #7** 2017-08-22 11:41**MOT test number** 844878597107**Result** ✓ Passed**MOT #6** 2016-08-17 16:26**MOT test number** 722341295438**Result** ✓ Passed**MOT #5** 2016-08-17 16:26**MOT test number** 766963090163**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)

**MOT #4** 2015-08-24 13:51**MOT test number** 129716935214**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)**Notice** Under-trays fitted obscuring some underside components**MOT #3** 2014-10-22 10:30**MOT test number** 967285094222**Result** ✓ Passed**MOT #2** 2013-09-23 09:57**MOT test number** 687996163298**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #1** 2012-09-26 14:11**MOT test number** 317980772262**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
29 November 2024

Tax status	Valid until 1 March
Days left	306
MOT expiry date	29 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-10-22
Last registration	2023-11-30
Complete history	See info



Registration #1	2009-10-22	28 mi
Registration #2	2012-09-26	38.802 mi
Registration #3	2013-09-23	51.603 mi
Registration #4	2014-10-22	60.425 mi
Registration #5	2015-08-24	65.737 mi
Registration #6	2016-08-17	75.457 mi
Registration #7	2016-08-17	75.457 mi
Registration #8	2017-08-22	83.355 mi
Registration #9	2018-08-17	94.877 mi
Registration #10	2018-08-22	94.877 mi
Registration #11	2019-08-22	106.399 mi
Registration #12	2020-08-22	117.921 mi
Registration #13	2021-08-22	129.443 mi
Registration #14	2022-08-22	140.965 mi
Registration #15	2023-08-22	152.487 mi
Registration #16	2023-08-22	152.487 mi
Registration #17	2023-08-22	152.487 mi
Registration #18	2023-08-22	152.487 mi
Registration #19	2023-08-22	152.487 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1408 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number

884000