



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	PASSAT S TDI BLUEMOTION TECHNOLOGY
Colour	Grey
Year of manufacture	2015
Top speed	127 mph
0 - 100 km/h	11.0 seconds
0 - 60 mph	11.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	88 kW / 120 HP / 118 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	58.9 mpg
Consumption extra urban	76.3 mpg
Consumption combined	68.9 mpg
CO2 emission	107 g/km
CO2 label	B






## Internet history

### Entry 3

Date	2022-09-18
Pictures	12
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

### Entry 2

Date	2021-07-28
Pictures	16
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 1

Date	2021-07-24
Pictures	16
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-11-22
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	26
Total items failed	7

MOT #11	2023-11-23 12:38
MOT test number	634609074144
Result	✓ Passed
Next expiry date	2024-11-22

MOT #10	2022-11-15 11:53
MOT test number	186194312940
Result	✓ Passed

MOT #9	2022-04-08 14:16
MOT test number	899804707743
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8** 2022-04-05 15:11**MOT test number** 399012160836**Result** ✗ Failed**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))**MOT #7** 2021-04-26 09:41**MOT test number** 589862495118**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Coil springs corroded**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Engine covers and under trays fitted obscuring some components**Advice** Brakes require further inspection**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2020-06-03 15:43**MOT test number** 220903713005**Result** ✓ Passed**Advice** Coil springs corroded**Advice** Engine covers and under trays fitted obscuring some components

**MOT #5** 2020-06-03 09:51**MOT test number** 883930747492**Result** ✗ Failed**Advice** Coil springs corroded**Fail** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Engine covers and under trays fitted obscuring some components**Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MOT #4** 2019-04-05 13:48**MOT test number** 272037584149**Result** ✓ Passed**Advice** Offside Front Seat belt slightly damaged (7.1.2 (b) (i))**Advice** Engine covers and under trays fitted obscuring some components**Advice** Coil springs corroded**MOT #3** 2019-04-02 14:28**MOT test number** 672895321597**Result** ✗ Failed**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Engine covers and under trays fitted obscuring some components**Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Offside Front Seat belt slightly damaged (7.1.2 (b) (i))**Advice** Coil springs corroded



MOT #2	2018-04-23 13:41
MOT test number	541736486884
Result	✓ Passed
Advice	Engine covers and under trays fitted obscuring some components
Advice	Coil springs corroded

MOT #1	2017-04-28 11:53
MOT test number	103465675155
Result	✓ Passed
Advice	Coil springs corroded
Advice	Engine covers and under trays fitted obscuring some components
Advice	Brakes require further inspection



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>GD65YXF</b>
Plate since	2020-03-29
Current registration	 <b>GD65YXF</b>
Plate since	2020-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2015-12-01
Last registration	2023-11-23
Complete history	<a href="#">See info</a>



Registration #1	2015-12-01	11 mi
Registration #2	2017-04-28	14.203 mi
Registration #3	2018-04-23	48.476 mi
Registration #4	2019-04-02	80.216 mi
Registration #5	2019-04-05	80.256 mi
Registration #6	2020-06-03	107.577 mi
Registration #7	2020-06-03	107.577 mi
Registration #8	2021-04-26	129.096 mi
Registration #9	2023-11-23	129.096 mi
Registration #10	2023-11-23	129.096 mi
Registration #11	2023-11-23	129.096 mi
Registration #12	2023-11-23	129.096 mi
Registration #13	2023-11-23	129.096 mi
Registration #14	2023-11-23	129.096 mi
Registration #15	2023-11-23	129.096 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	85%
Children	87%
Pedestrian	66%
Safety systems	76%
Overall rating	80%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1820 mm
Height	1516 mm
Length	4771 mm
Wheel base	2712 mm
Kerb weight	1400 kg
Max. allowed weight	2060 kg

Additional information

Fuel tank capacity	59 l
Fuel delivery	Direct Injection
Number of doors	5

Number of axles	2
Engine number	DCXA009039