





report date: 2024-03-29

General information

Make	FIAT
Model	DOBLO 16V MULTIJET
Colour	Red
Year of manufacture	2016
Top speed	102 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	290 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	61.4 mpg
Consumption combined	54.3 mpg
CO2 emission	144 g/km
CO2 label	F



CarCheck.co.uk page 1/11



BV66BVL report date: 2024-03-29

Internet history

Entry 1

Date 2022-03-06

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

MOT expiry date	2024-09-06
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	11
Total items failed	3

MOT #7		2023-09-07 14:54
MOT test	number	543822322162
Result		✓ Passed
Next expi	ry date	2024-09-06
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Rear Exhaust noisy back box corroded (8.1.1 (a))	

MOT #6	2023-09-07 09:26
MOT test number	858516818664
Result	× Failed
Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to rea (5.2.3 (d) (i))	ach the ply or cords
Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Rear Exhaust noisy back box corroded (8.1.1 (a))	
Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #5

MOT test number

268997526639

Result

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #4

MOT test number

236082230345

Result

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #3

MOT test number

158758351113

Result

✓ Passed

MOT #2

MOT test number

401691530201

Result

Pass with rectification

Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

 MOT #1
 2019-08-22 15:13

 MOT test number
 898721093470

 Result
 ✓ Passed

CarCheck.co.uk page 4/11



BV66BVL report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 June
Days left	32
MOT expiry date	6 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 5/11




report date: 2024-03-29

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report $\underline{\mathbf{k}}$	
HARMAN CO. C.	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	NIE.
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
011.1.5	

Contact info

More info >

CarCheck.co.uk page 9/11



BV66BVL report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-09-02
Last registration	2023-09-07
Complete history	See info



Registration #1	2016-09-02	14 mi
Registration #2	2019-08-22	46.745 mi
Registration #3	2020-08-21	60.390 mi
Registration #4	2020-08-21	60.390 mi
Registration #5	2021-08-31	67.847 mi
Registration #6		71.777 66
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
60482	
60501	
60566	
60567	
50569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1832 mm
Height	1845 mm
Length	4390 mm
Kerb weight	1445 kg
Max. allowed weight	2465 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	7611922

CarCheck.co.uk page 11/11