



FY59KPN

report date: 2024-03-28

General information

Make	VOLVO
Model	C70 D S
Colour	Silver
Year of manufacture	-
Top speed	127 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	57.6 mpg
Consumption combined	47.1 mpg





Internet history

Entry 1

Date	2021-09-04
Pictures	33
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #15	2021-10-05 11:03
MOT test number	857970461223
Result	✓ Passed
Next expiry date	2022-10-04
Advice	Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))
Advice	Central Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))

MOT #14	2021-10-04 13:55
MOT test number	547615360308
Result	✗ Failed
Fail	Central Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))
Fail	Emissions not tested hole in rear silencer (8.2.2.2 (e))
Advice	Central Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
Fail	Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
Fail	Central Exhaust system insecure hanger not attached to floor (6.1.2 (a))

MOT #13	2020-08-20 14:59
MOT test number	515773315973
Result	✓ Passed

**MOT #12**

2020-08-19 08:49

MOT test number

303325522304

Result

✗ Failed

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #11**

2019-08-16 10:09

MOT test number

196202687508

Result

✓ Passed

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #10**

2018-08-29 09:28

MOT test number

476305059630

Result

✓ Passed

**MOT #9** 2018-08-28 15:03**MOT test number** 120040576247**Result** ✗ Failed

Fail Nearside Front Inner Suspension arm attachment bracket/mounting likely to become detached (5.3.3 (a) (ii))

Fail Offside Rear Inner Suspension arm attachment bracket/mounting likely to become detached (5.3.3 (a) (ii))

MOT #8 2017-09-04 08:38**MOT test number** 202341108407**Result** ✓ Passed

Advice Offside Front Outer Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

MOT #7 2016-09-05 11:24**MOT test number** 725932826297**Result** ✓ Passed

Advice Child Seat fitted not allowing full inspection of adult belt

Advice Offside Rear Anti-roll bar has slight play in a ball joint (2.4.G.2)

MOT #6 2016-09-05 09:52**MOT test number** 928612340276**Result** ✗ Failed

Fail Parking brake: efficiency below requirements (3.7.B.7)

Advice Offside Rear Anti-roll bar has slight play in a ball joint (2.4.G.2)

Pass with rectification Nearside Stop lamp not working (1.2.1b)

Advice Child Seat fitted not allowing full inspection of adult belt

**MOT #5** 2015-09-05 07:34**MOT test number** 750560589672**Result** ✓ Passed**Advice** Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #4** 2015-09-04 09:16**MOT test number** 173104207722**Result** ✗ Failed**Fail** Nearside Inner Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #3** 2014-09-15 13:27**MOT test number** 969948654224**Result** ✓ Passed**Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #2** 2013-08-07 13:40**MOT test number** 907539013274**Result** ✓ Passed**MOT #1** 2012-08-23 13:53**MOT test number** 675276932223**Result** ✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-09-02
Last registration	2021-10-05
Complete history	See info



Registration #1	2009-09-02	8 mi
Registration #2	2012-08-23	67.509 mi
Registration #3	2013-08-07	82.443 mi
Registration #4	2014-09-15	99.494 mi
Registration #5	2015-09-04	114.985 mi
Registration #6	2015-09-05	114.991 mi
Registration #7	2016-09-05	126.105 mi
Registration #8	2016-09-05	126.105 mi
Registration #9	2017-09-04	132.531 mi
Registration #10	2018-09-04	132.531 mi
Registration #11	2019-09-04	132.531 mi
Registration #12	2020-09-04	132.531 mi
Registration #13	2021-09-04	132.531 mi
Registration #14	2022-09-04	132.531 mi
Registration #15	2023-09-04	132.531 mi
Registration #16	2024-09-04	132.531 mi
Registration #17	2025-09-04	132.531 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1400 mm
Length	4582 mm
Wheel base	2640 mm
Kerb weight	1715 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Engine number	623857
---------------	--------