



report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO ACTIVE
Colour	Blue
Year of manufacture	2008
Top speed	96 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	64 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-05-29
Pictures	22
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-05-03
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	30
Total items failed	5

MOT #18	2023-05-04 11:38
MOT test number	915765252723
Result	✓ Passed
Next expiry date	2024-05-03

MOT #17	2023-05-02 15:31
MOT test number	957655956649
Result	✗ Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Front Lower Exhaust has a major leak of exhaust gases (6.1.2 (a))

MOT #16	2022-02-18 12:05
MOT test number	260157654679
Result	✓ Passed
Advice	Child Seat fitted not allowing full inspection of adult belt

MOT #15	2021-02-19 09:53
MOT test number	556605785759
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14**

2021-02-19 09:53

**MOT test number**

579796351901

**Result****✗ Failed****Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #13**

2020-02-03 16:41

**MOT test number**

160650891563

**Result****✓ Passed****Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))**Advice** Oil leak, but not excessive Top of engine, breather hose area. (8.4.1 (a) (i))**Minor** Offside Front Lower Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Minor** Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Oil leak, but not excessive Transmission drive shaft seal . (8.4.1 (a) (i))

**MOT #12**

2020-02-03 16:41

**MOT test number**

959136302705

**Result**

✗ Failed

**Minor** Offside Front Lower Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))**Pass with rectification** Nearside Rear Upper Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Oil leak, but not excessive Transmission drive shaft seal . (8.4.1 (a) (i))**Minor** Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Oil leak, but not excessive Top of engine, breather hose area. (8.4.1 (a) (i))**MOT #11**

2019-02-15 16:14

**MOT test number**

921047912629

**Result**

✓ Passed

**Minor** Offside Front Lower Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))**Minor** Nearside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))**Advice** Offside Front Outer Tyre slightly damaged/cracking or perishing Sidewall slightly damaged/scrubbed. (5.2.3 (d) (ii))**Advice** Oil leak, but not excessive Suspect N/S drive shaft oil seal. (8.4.1 (a) (i))**MOT #10**

2018-02-19 16:17

**MOT test number**

856171221218

**Result**

✓ Passed

**Advice** Damage to rear lower bumper

**MOT #9** 2017-06-01 13:58**MOT test number** 233191680234**Result** ✓ Passed**Advice** Rear Bumper insecure lower split**MOT #8** 2016-06-09 15:59**MOT test number** 775373983172**Result** ✓ Passed**MOT #7** 2016-06-09 13:55**MOT test number** 545464192552**Result** ✗ Failed**Advice** Cracks in offside & nearside front tyres not to cord**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Engine oil level low**Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #6** 2015-06-11 16:38**MOT test number** 136122365179**Result** ✓ Passed**MOT #5** 2015-06-11 10:28**MOT test number** 209932165146**Result** ✗ Failed**Fail** Nearside Front coil spring broken (2.4.C.1a)**MOT #4** 2014-05-08 10:08**MOT test number** 187958224105**Result** ✓ Passed



MOT #3	2013-05-09 09:35
MOT test number	989229923133
Result	✓ Passed
MOT #2	2012-05-23 09:41
MOT test number	138174842145
Result	✓ Passed
MOT #1	2011-05-24 10:20
MOT test number	128184341178
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
11 December 2023

✓

MOT

Expires:  
3 May 2024

Tax status	Expired at 11 December 2023
Days left	140 days too late
MOT expiry date	3 May 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-05-30
Last registration	2023-05-04
Complete history	<a href="#">See info</a>



Registration #1	2008-05-30	7 mi
Registration #2	2011-05-24	20.582 mi
Registration #3	2012-05-23	21.744 mi
Registration #4	2013-05-09	22.367 mi
Registration #5	2014-05-08	23.822 mi
Registration #6	2015-06-11	24.948 mi
Registration #7	2015-06-11	24.948 mi
Registration #8	2016-06-09	30.813 mi
Registration #9	2016-06-09	30.813 mi
Registration #10	2017-06-01	37.797 mi
Registration #11	2018-06-01	38.000 mi
Registration #12	2019-06-01	38.000 mi
Registration #13	2020-06-01	38.000 mi
Registration #14	2021-06-01	38.000 mi
Registration #15	2022-06-01	38.000 mi
Registration #16	2023-06-01	38.000 mi
Registration #17	2024-06-01	38.000 mi
Registration #18	2025-06-01	38.000 mi
Registration #19	2026-06-01	38.000 mi
Registration #20	2027-06-01	38.000 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	4363732