



Mercedes-Benz




report date: 2024-03-28

General information

Make	MERCEDES
Model	ML ML 320 CDI EDITION 10
Colour	Silver
Year of manufacture	2008
Top speed	127 mph
Gearbox	7 speed automatic

Engine & fuel consumption

Power	221 BHP
Max. torque	510 Nm at 2.800 rpm
Engine capacity	2.987 cc
Cylinders	6
Fuel type	Diesel
Consumption city	22.1 mpg
Consumption extra urban	36.2 mpg
Consumption combined	29.4 mpg
CO2 emission	254 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-10-06
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-04-21
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	37
Total items failed	6

MOT #17	2024-04-27 13:02
MOT test number	531126752871
Result	✗ Failed
MAJOR	Offside Front Brake hose excessively deteriorated (1.1.12 (b) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #16	2023-04-12 12:07
MOT test number	447981375954
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #15** 2022-04-22 16:05**MOT test number** 879863699827**Result** ✓ Passed**MOT #14** 2022-04-11 14:31**MOT test number** 838771810421**Result** ✗ Failed

MAJOR Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MAJOR Offside Front Brake pipe excessively corroded to rear (1.1.11 (c))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MAJOR Offside Parking brake inoperative on one side (1.4.1 (a))

MAJOR Nearside Front Brake pipe excessively corroded to rear (1.1.11 (c))

DANGEROUS Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MAJOR Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

MOT #13 2022-03-02 14:10**MOT test number** 375639587146**Result** ✗ Failed

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MAJOR Nearside Rear Brake pipe excessively corroded to flexible brake hose (1.1.11 (c))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MAJOR Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MAJOR Offside Rear Brake pipe excessively corroded to flexible brake hose (1.1.11 (c))

**MOT #12** 2021-10-18 11:42**MOT test number** 525139318421**Result** ✓ Passed**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #11** 2020-12-08 10:34**MOT test number** 460411949035**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2019-12-03 15:56**MOT test number** 674886795011**Result** ✓ Passed**MOT #9** 2018-12-06 13:56**MOT test number** 267520706216**Result** ✓ Passed**MOT #8** 2017-12-21 17:53**MOT test number** 334557094352**Result** ✓ Passed

**MOT #7** 2017-12-21 11:17**MOT test number** 779849577391**Result** ✗ Failed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)**Fail** Offside Rear coil spring broken (2.4.C.1a)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #6** 2017-04-20 11:59**MOT test number** 554612119169**Result** ✓ Passed**MOT #5** 2015-04-30 10:45**MOT test number** 456270525194**Result** ✓ Passed**Notice** Oil level below minimum**Notice** N/s/r shocker leaking**Notice** Under-trays fitted obscuring some underside components**MOT #4** 2014-05-01 10:48**MOT test number** 465951424134**Result** ✓ Passed**Notice** Oil leak on engine**Notice** O/s/f tyre worn on inside and outside edges



MOT #3	2014-04-25 10:14
MOT test number	505345714169
Result	✗ Failed
Fail	Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)
Pass with rectification	Nearside Stop lamp not working (1.2.1b)
Notice	Oil leak on engine
Pass with rectification	Offside Headlamp not working on dipped beam (1.7.5a)
Notice	O/s/f tyre worn on inside and outside edges

MOT #2	2013-04-22 09:52
MOT test number	919952213144
Result	✓ Passed
Notice	Oil leak on engine
Notice	Child locks on rear doors
Notice	N/s/r tyre worn close to marker bars and scuffed on outer wall

MOT #1	2011-11-03 12:24
MOT test number	805167701362
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 August 2024

✗
MOT

Expired:
21 April 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	21 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 BV58UNW
Plate since	2019-06-29
Current registration	 BV58UNW
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-09-05
Last registration	2024-04-27
Complete history	See info



Registration #1	2008-09-05	11 mi
Registration #2	2011-11-03	32.041 mi
Registration #3	2013-04-22	45.395 mi
Registration #4	2014-04-25	61.898 mi
Registration #5	2014-05-01	62.183 mi
Registration #6	2015-04-30	71.059 mi
Registration #7	2017-04-20	106.654 mi
Registration #8	2017-12-21	113.644 mi
Registration #9	2017-12-21	113.644 mi
Registration #10	2018-12-06	116.925 mi
Registration #11	2019-05-20	121.277 mi
Registration #12	2019-05-20	121.277 mi
Registration #13	2019-05-20	121.277 mi
Registration #14	2019-05-20	121.277 mi
Registration #15	2019-05-20	121.277 mi
Registration #16	2019-05-20	121.277 mi
Registration #17	2019-05-20	121.277 mi
Registration #18	2019-05-20	121.277 mi
Registration #19	2019-05-20	121.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1911 mm
Height	1815 mm
Length	4780 mm
Wheel base	2915 mm
Kerb weight	2185 kg
Max. allowed weight	2830 kg

Additional information

Fuel tank capacity	95 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	64294040672802