





report date: 2024-03-28

#### General information

Make	VOLKSWAGEN
Model	SCIROCCO R TSI
Colour	White
Year of manufacture	2015
Top speed	155 mph
0 - 60 mph	5.7 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	278 BHP
Max. torque	350 Nm at 2.500 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	45.6 mpg
Consumption combined	34.9 mpg
CO2 emission	187 g/km
CO2 label	J



CarCheck.co.uk page 1/11



report date: 2024-03-28

### Internet history

#### Entry 1

Date 2021-02-06

Pictures 4

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-10-01
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	8
Total items failed	3

MOT #10	2023-09-29 08:59
MOT test number	796828605032
Result	<b>✓</b> Passed
Next expiry date	2024-10-01

MOT #9	2022-09-30 10:20
MOT test number	198283859007
Result	<b>✓</b> Passed

MOT #8	2021-10-02 12:02
MOT test number	350276031849
Result	✓ Passed

MOT #7	2021-10-02 09:02

**MOT test number** 187934102117

Result

Fail Rear Registration plate missing (0.1 (a))

X Failed

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge Tread wearing on inner edge (5.2.3 (e))

**Fail** Offside Front Service brake excessively fluctuating (1.2.1 (e))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing Outer side wall (5.2.3 (d) (ii))

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #6 2021-04-30 07:54

**MOT test number** 594165828738

**Result** ✓ Passed

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement CONSOLE (5.3.4 (a) (i))

**Advice** Nearside rear tyre sawtoothing at inner edge

MOT #5 2021-04-28 16:31

**MOT test number** 653812913101

Result X Failed

Fail Exhaust has a major leak of exhaust gases (6.1.2 (a))

Advice Nearside rear tyre sawtoothing at inner edge

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement CONSOLE (5.3.4 (a) (i))

**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #4 2020-10-13 13:38

**MOT test number** 938710990417

MOT #3 2020-03-06 10:52

**MOT test number** 176876208029

**Result** ✓ Passed

**MOT #2** 2019-03-08 08:46

**MOT test number** 605131740135

MOT #1 2018-03-09 13:10

**MOT test number** 434854077477

Result 

Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 May
Days left	367
MOT expiry date	1 October 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

#### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

#### Damage 1

Date	
Category	
Туре	

Damage 2	
Date	
Category	



#### Extra VOLKSWAGEN salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

# Owner history

Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	
***************************************	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-11-05
Last registration	2023-09-29
Complete history	See info



Registration #1	2015-11-05	10 mi
Registration #2	2018-03-09	21.474 mi
Registration #3	2019-03-08	28.271 mi
Registration #4	2020-03-06	34.342 mi
Registration #5	2020-10-13	35.979 mi
Registration #6		11.777 es
Registration #7		9.777 es
Registration #8		11.777 es
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.117 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

#### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	87%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	76%
Video	see crash video



## Dimensions & weight

Width	1810 mm
Height	1404 mm
Length	4256 mm
Wheel base	2578 mm
Kerb weight	1318 kg
Max. allowed weight	1770 kg

#### Additional information

Fuel tank capacity	55 I
Fuel delivery	Direct Injection
Number of doors	2
CarChack co.uk	nago 11/11

CarCheck.co.uk page 11/11

Number of seats	4
Number of axles	2
Engine number	CDLK103620