



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	CLK CLK280 AVANTGARDE
Colour	Black
Year of manufacture	2007
Top speed	150 mph
Gearbox	7 speed automatic

Engine & fuel consumption

Power	228 BHP
Max. torque	300 Nm at 3.000 rpm
Engine capacity	2.997 cc
Cylinders	6
Fuel type	Petrol
Consumption city	20.8 mpg
Consumption extra urban	38.7 mpg
Consumption combined	29.4 mpg
CO2 emission	227 g/km
CO2 label	L





Internet history

Entry 2

Date	2021-08-28
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-07-18
Pictures	43
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-07-09
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	21
Total items failed	6

MOT #16	2023-07-10 08:35
MOT test number	136077779401
Result	✓ Passed
Next expiry date	2024-07-09
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15	2023-07-06 09:38
MOT test number	860315695289
Result	✗ Failed
Fail	Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14	2022-06-30 08:58
MOT test number	563039229463
Result	✓ Passed

MOT #13	2021-07-09 16:10
MOT test number	706020593275
Result	✓ Passed

**MOT #12** 2020-05-22 08:49**MOT test number** 838773967901**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Advice** Front Brake pad(s) wearing thin both (1.1.13 (a) (ii))**MOT #11** 2019-05-30 16:18**MOT test number** 764556812905**Result** ✓ Passed**MOT #10** 2019-05-30 12:45**MOT test number** 367325746782**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #9** 2018-06-16 08:30**MOT test number** 413008283256**Result** ✓ Passed**MOT #8** 2016-07-06 12:13**MOT test number** 399013127010**Result** ✓ Passed**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

**MOT #7** 2015-03-31 12:57**MOT test number** 807190795037**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Nearside and offside front tyres wearing on inner edges**MOT #6** 2014-02-27 11:58**MOT test number** 187888954448**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #5** 2013-03-18 11:45**MOT test number** 638837173031**Result** ✓ Passed**MOT #4** 2013-03-14 12:32**MOT test number** 197683673019**Result** ✗ Failed**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

**MOT #3** 2012-03-22 16:15**MOT test number** 395672982010**Result** ✓ Passed

**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #2** 2010-04-01 14:50**MOT test number** 454191990086**Result** ✓ Passed**MOT #1** 2010-03-26 11:19**MOT test number** 781455080051**Result** ✗ Failed

**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2025

✓  
**MOT**  
**Expires:**  
9 July 2024

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	367
<b>MOT expiry date</b>	9 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	L
<b>Single payment (12 months)</b>	£ 675,00,-
<b>Single six month payment</b>	£ 371,25,-
<b>Total payable by 12 monthly instalments</b>	£ 708,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-03-29
Last registration	2023-07-10
Complete history	<a href="#">See info</a>



Registration #1	2007-03-29	6 mi
Registration #2	2010-03-26	27.996 mi
Registration #3	2010-04-01	28.237 mi
Registration #4	2012-03-22	30.891 mi
Registration #5	2013-03-14	34.450 mi
Registration #6	2013-03-18	34.488 mi
Registration #7	2014-02-27	37.780 mi
Registration #8	2015-03-31	40.484 mi
Registration #9	2016-07-06	45.456 mi
Registration #10	2018-06-16	50.599 mi
Registration #11	2019-05-29	51.277 mi
Registration #12	2019-05-29	51.277 mi
Registration #13	2019-05-29	51.277 mi
Registration #14	2019-05-29	51.277 mi
Registration #15	2019-05-29	51.277 mi
Registration #16	2019-05-29	51.277 mi
Registration #17	2019-05-29	51.277 mi
Registration #18	2019-05-29	51.277 mi
Registration #19	2019-05-29	51.277 mi

More info >



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2690 mm
Kerb weight	1705 kg
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27294030602112