





report date: 2024-03-29

General information

Make	VAUXHALL
Model	COMBO 2000 L1H1 CDTI
Colour	Silver
Year of manufacture	2015
Top speed	97 mph
0 - 60 mph	15.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	67.3 mpg
Consumption combined	56.5 mpg
CO2 emission	133 g/km
CO2 label	E



CarCheck.co.uk page 1/12



Internet history


Entry 1

Date 2021-01-21

Pictures 11

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-12-20
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	13
Total items failed	7

MOT #10		2023-12-13 14:35
MOT test i	number	702640916904
Result		✓ Passed
Next expir	y date	2024-12-20
Advice Front Tyre worn close to legal limit/worn on edge o/s n/s (5.2.3 (e))		
Advice	Rear Coil spring corroded o/s n/s (5.3.1 (b) (i))	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened o/s n/s (1.1.14 (a) (ii))		/s (1.1.14 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #9	2022-12-21 16:47
MOT test number	914382817861
Result	✓ Passed
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear (5.3.4 (a) (i)) Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



DY15WXB

report date: 2024-03-29

MOT #8 2022-12-21 09:14 642847274127 **MOT** test number Result × Failed Fail Hazard warning switch inoperative (4.4.2 (a) (ii)) Fail Battery insecure and likely to fall from carrier (4.13 (a) (ii)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Rear fog lamp switch inoperative (4.5.3 (a)) **Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear (5.3.4 (a) (i))

MOT #7

MOT test number

480270673586

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

 MOT #6
 2020-11-25 13:15

 MOT test number
 156684250438

 Result
 ✓ Passed

MOT test number

Result

Pass with rectification

Rear Registration plate does not conform to the specified requirements (0.1 (d))

Pass with rectification

Rear fog lamp tell-tale not working (4.9.1 (a) (ii))

Pass with rectification

Rear fog lamp not working (4.5.1 (a) (ii))

CarCheck.co.uk page 4/12



DY15WXB

report date: 2024-03-29

MOT #4		2020-02-21 14:05
MOT test i	number	482216256226
Result		✓ Passed
Advice	Clutch pedal pad missing	
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	

MOT #3		2020-02-20 16:52
MOT test	number	314514703381
Result		× Failed
Advice	Clutch pedal pad missing	
Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))		
Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))		

MOT #2	2019-03-13 12:45
MOT test number	431291227810
Result	✓ Passed
MOT #1	2018-03-02 17:25
MOT test number	158338657158
Result	✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	20 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category
Type

Damage 2

Date

Category

Type



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history	
For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downloaner.	

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	K UK
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-03-06
Last registration	2023-12-13
Complete history	See info



Registration #1	2015-03-06	15 mi
Registration #2	2018-03-02	40.791 mi
Registration #3	2019-03-13	46.022 mi
Registration #4	2020-02-20	51.188 mi
Registration #5	2020-02-21	51.188 mi
Registration #6	2020-11-25	51.639 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		111.7777 ess
Registration #11		10.107 es
Registration #12		11.777 mg

More info >

CarCheck.co.uk page 11/12



Dimensions & weight

Width	2119 mm
Height	1845 mm
Length	4390 mm
Kerb weight	1270 kg
Max. allowed weight	2040 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	263A20005688130 LN9

CarCheck.co.uk page 12/12