



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	CARAVELLE T30 SWB KOMBI 130TDI
Colour	Blue
Year of manufacture	2003
Top speed	101 mph
0 - 60 mph	15.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	128 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	2.460 cc
Cylinders	5
Fuel type	Diesel
Consumption city	26.2 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.3 mpg
CO2 emission	216 g/km
CO2 label	K






Internet history

Entry 1

Date	2021-10-13
Pictures	4
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-01-30
MOT pass rate	68 %
MOT passed	17
Failed MOT tests	8
Total advice items	35
Total items failed	10

MOT #25	2024-01-31 18:19
MOT test number	812870571355
Result	✓ Passed
Next expiry date	2025-01-30
Advice	Central Non obligatory mirror damaged offside
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #24	2023-01-17 13:13
MOT test number	192943462899
Result	✓ Passed

MOT #23	2023-01-16 15:12
MOT test number	512731851458
Result	✗ Failed
MAJOR	Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

MOT #22	2022-01-18 15:06
MOT test number	833655545310
Result	✓ Passed

**MOT #21** 2022-01-14 10:42**MOT test number** 266797188431**Result** ✗ Failed

**MAJOR** Offside Rear Seat belt anchorage prescribed area strength or continuity significantly reduced  
Corrosion sill (7.1.1 (a) (i))

**MOT #20** 2020-11-16 16:47**MOT test number** 653234469093**Result** ✓ Passed

**Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))

**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

**Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))

**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #19**

2020-11-13 16:46

**MOT test number**

215539272873

**Result****✗ Failed**

- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- MAJOR** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- DANGEROUS** Exhaust emits excessive smoke or vapour likely to obscure the vision of other road users (8.2.2.2 (c))
- Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- MAJOR** Exhaust emissions test not completed because smoke levels are significantly in excess of the specified limit values (8.2.2.2 (f))
- Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- MAJOR** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))

**MOT #18**

2019-11-06 15:15

**MOT test number**

312565560331

**Result****✓ Passed****MOT #17**

2019-11-06 15:15

**MOT test number**

227597130802

**Result****✗ Failed**

- Pass with rectification** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Pass with rectification** Electronic stability control warning lamp indicates a fault (7.12 (e))

**MOT #16** 2018-11-17 12:19**MOT test number** 486320270570**Result** ✓ Passed**MOT #15** 2017-11-09 17:16**MOT test number** 382380695149**Result** ✓ Passed**MOT #14** 2017-11-09 14:03**MOT test number** 871157968042**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**MOT #13** 2016-11-23 13:01**MOT test number** 920306146209**Result** ✓ Passed**MOT #12** 2016-11-23 13:01**MOT test number** 489906832616**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)

**MOT #11**

2015-11-07 13:42

**MOT test number**

995583750128

**Result**

✓ Passed

**Advice** O/s/f side mirror slightly cracked**Advice** Lower Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt both side (2.4.G.2)**Advice** Brake disc worn, pitted or scored, but not seriously weakened all around 4 (3.5.1i)**Advice** Gearbox mount has a slight play**MOT #10**

2015-11-06 17:28

**MOT test number**

503520486690

**Result**

✗ Failed

**Advice** Brake disc worn, pitted or scored, but not seriously weakened all around 4 (3.5.1i)**Advice** O/s/f side mirror slightly cracked**Fail** Headlamp aim beam image obviously incorrect both side (1.8.A.1b)**Fail** Rear coil spring corroded so that its cross sectional area is reduced and seriously weakened both side (2.4.C.1b)**Advice** Lower Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt both side (2.4.G.2)**Advice** Gearbox mount has a slight play**MOT #9**

2014-11-06 15:20

**MOT test number**

947680514385

**Result**

✓ Passed

**Advice** Nearside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Advice** Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**MOT #8**

2013-11-26 17:40

**MOT test number**

149240633325

**Result**

✓ Passed

**MOT #7** 2012-11-22 16:59**MOT test number** 227757922326**Result** ✓ Passed**Notice** N/s front tyre worn on outside edge**MOT #6** 2011-11-18 15:44**MOT test number** 445612221414**Result** ✓ Passed**MOT #5** 2010-07-23 17:36**MOT test number** 674714300224**Result** ✓ Passed**MOT #4** 2009-08-07 12:23**MOT test number** 650089119261**Result** ✓ Passed**MOT #3** 2008-01-30 13:33**MOT test number** 834730538067**Result** ✓ Passed**MOT #2** 2008-01-29 09:50**MOT test number** 884079028095**Result** ✗ Failed**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Rear Registration plate lamp not working (1.1.5c)





MOT #1	2006-12-05 14:17
MOT test number	342259936328
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
30 January 2025

Tax status		Valid until 1 October
Days left		154
MOT expiry date		30 January 2025
Full MOT history		<a href="#">See MOT history</a>

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>LS53PGY</b>
Plate since	2024-03-29
Current registration	 <b>LS53PGY</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	27
First mileage registration	2003-11-12
Last registration	2024-01-31
Complete history	<a href="#">See info</a>



Registration #1	2003-11-12	11 mi
Registration #2	2006-12-05	27.289 mi
Registration #3	2008-01-29	31.401 mi
Registration #4	2008-01-30	31.401 mi
Registration #5	2009-08-07	36.383 mi
Registration #6	2010-07-23	38.832 mi
Registration #7	2011-11-18	42.576 mi
Registration #8	2012-11-22	46.845 mi
Registration #9	2013-11-26	51.667 mi
Registration #10	2014-11-06	56.124 mi
Registration #11	2015-11-06	60.176 mi
Registration #12	2015-11-07	60.177 mi
Registration #13	2016-11-23	63.008 mi
Registration #14	2016-11-23	63.008 mi
Registration #15	2016-11-23	63.008 mi
Registration #16	2016-11-23	63.008 mi
Registration #17	2016-11-23	63.008 mi
Registration #18	2016-11-23	63.008 mi
Registration #19	2016-11-23	63.008 mi
Registration #20	2016-11-23	63.008 mi
Registration #21	2016-11-23	63.008 mi
Registration #22	2016-11-23	63.008 mi
Registration #23	2016-11-23	63.008 mi
Registration #24	2016-11-23	63.008 mi
Registration #25	2016-11-23	63.008 mi
Registration #26	2016-11-23	63.008 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2175 mm
Height	1940 mm
Length	4707 mm

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Engine number	AXD 022865