





report date: 2024-03-28

#### General information

Make	RENAULT
Model	TRAFIC LL29 SPORT NAV DCI
Colour	Black
Year of manufacture	2017
Top speed	103 mph
0 - 100 km/h	12.6 seconds
0 - 60 mph	12.6 seconds
Gearbox	6 speed Manual

#### Engine & fuel consumption

Power	89 kW / 121 HP / 120 BHP
Max. torque	300 Nm at 1.500 rpm
<b>Engine capacity</b>	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	49.6 mpg
Consumption combined	43.5 mpg
CO2 emission	174 g/km
CO2 label	Н



CarCheck.co.uk page 1/12



report date: 2024-03-28

### Internet history

#### Entry 1

Date 2022-04-09

Pictures 43

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

### MOT history

MOT expiry date	2025-04-13
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	10
Total items failed	7

MOT #9	2024-04-08 11:06
MOT test number	497583277217
Result	✓ Passed
Next expiry date	2025-04-13
Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	

MOT #8		2023-04-03 12:39
MOT test r	number	141378171171
Result		✓ Passed
Advice	Nearside Rear Nail in tyre	
Advice	Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))	

MOT #7	2023-04-03 12:39
MOT test number	167278164422
Result	<b>X</b> Failed
Advice Nearside Rear Nail in tyre	
Advice Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))	
Pass with rectification Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #6 2022-04-14 15:40 MOT test number 258305952405

**Result** ✓ Passed

MOT #5 2021-07-01 11:08

**MOT test number** 540223255121

**Advice** Under tray fitted

**MOT #4** 2021-06-30 08:49

**MOT test number** 120276699006

Result X Failed

**Fail** Offside Rear Reversing lamp inoperative (4.6.1 (a))

**Advice** Under tray fitted

Fail Nearside Front Service brake excessively fluctuating (1.2.1 (e))

**Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure inner and outer sidewall (5.2.3 (d) (ii))

**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

Advice Front Brake pad(s) wearing thin approx 2mm (1.1.13 (a) (ii))

MOT #3 2020-07-01 08:04

**MOT test number** 627037867608

Result 


Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28





CarCheck.co.uk page 5/12



report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 April
Days left	338
MOT expiry date	13 April 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

#### Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

## Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
HARMAN CONTRACTOR CONT	
THE PROPERTY OF THE PROPERTY O	
***************************************	
	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	ZIS UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

#### Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-05-08
Last registration	2024-04-08
Complete history	See info



Registration #1	2017-05-08	8 mi
Registration #2	2020-06-30	94.958 mi
Registration #3	2020-07-01	94.960 mi
Registration #4	2021-06-30	57.513 mi
Registration #5	2021-07-01	57.515 mi
Registration #6		11.777 es
Registration #6 Registration #7		11.777 es
		11.777 es 11.777 es
Registration #7		11.777 ea 11.777 ea 11.777 ea

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

### Car features

50225	Air conditionin
50295	
50482	
60501	
60566	
60567	
50569	

## Safety ratings

NCAP rating	***
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	see crash video



## Dimensions & weight

Width	2283 mm
Height	1971 mm
Length	5399 mm
Wheel base	3498 mm
Kerb weight	1750 kg
Max. allowed weight	3030 kg

# Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats CarCheck.co.uk	3 page 12/

Number of axles2Engine numberC091816