





report date: 2024-03-29

General information

Make	FIAT
Model	500L MULTIJET LOUNGE DUALOGIC
Colour	Silver
Year of manufacture	2014
Top speed	102 mph
0 - 60 mph	15.1 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	85 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	76.4 mpg
Consumption combined	70.6 mpg
CO2 emission	105 g/km
CO2 label	В



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Εn	itrv	2

Date	2023-03-27
Pictures	0
Listing price	<u>View report</u>

source: carcraft.co.uk

Entry 1

Lifting 1	
Date	2022-03-11
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2024-04-06
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	11
Total items failed	3

MOT #8	2023-04-04 07:54
MOT test number	555988805500
Result	✓ Passed
Next expiry date	2024-04-06

MOT #7	2022-04-07 10:08
MOT test number	630909341797
Result	✓ Passed

MOT #6		2021-11-30 08:16
MOT test	number	365338423773
Result		✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened borderlin	ne fail !! (1.1.14 (a)
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #5 2021-11-28 11:36

MOT test number 916967156811

Result X Failed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Central Rear Seat belt buckle missing (7.1.2 (d))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened borderline fail !! (1.1.14 (a) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Fail Driver's view of the road through the swept area of the windscreen significantly affected by an obstruction (3.1 (a) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4 2020-12-01 16:04

MOT test number 737834382319

Result
✓ Passed

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #3 2019-05-23 11:53

MOT test number 248565087010

Result ✓ Passed

MOT #2 2018-05-29 10:37

MOT test number 564888585362

Result
✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #1 2017-04-08 11:31

MOT test number 465448563070

Result ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 April
Days left	338
MOT expiry date	6 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	NK SIK
Plate since	
	More info

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-04-07
Last registration	2023-04-04
Complete history	See info



Registration #1	2014-04-07	29 mi
Registration #2	2017-04-08	25.187 mi
Registration #3	2018-05-29	32.760 mi
Registration #4	2019-05-23	40.902 mi
Registration #5	2020-12-01	50.385 mi
Registration #6	2021-11-28	59.255 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.77 44
Registration #11		71.777 mg

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	94%
Children	78%
Pedestrian	65%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2018 mm
Height	1667 mm
Length	4147 mm
Kerb weight	1320 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 12/12

5491039