



R008PYU

report date: 2024-03-28

General information

Make	FORD
Model	KA STUDIO
Colour	Black
Year of manufacture	-
Top speed	104 mph
0 - 60 mph	14.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	106 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	57.7 mpg
Consumption combined	45.6 mpg






Internet history

Entry 1

Date	2021-06-09
Pictures	5
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT #12	2021-10-20 12:11
---------	------------------

MOT test number	611532244271
-----------------	--------------

Result	✗ Failed
--------	----------

MAJOR Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MAJOR Offside Rear Inner Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))

MAJOR Nearside Headlamp aim not tested (4.1.2 (b))

Advice Central Exhaust mounting defective (6.1.2 (a))

MAJOR Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MAJOR Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Advice Battery light on

MAJOR Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MAJOR Nearside Rear Inner Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))

Advice Imbalance on front brakes

MAJOR Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MAJOR Offside Rear Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))

MAJOR Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Advice Front floor corroded

MAJOR Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

MAJOR Offside Front Inner Suspension component mounting prescribed area excessively corroded significantly reducing structural strength wheel arch (5.3.6 (a) (i))

Advice Exhaust corroded

MOT #11	2020-10-01 09:02
---------	------------------

MOT test number	805750961506
-----------------	--------------

Result	✓ Passed
--------	----------

Advice

Central Front exhaust hanger snapped



MOT #10	2019-03-30 12:10
----------------	------------------

MOT test number	828503108670
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #9	2018-04-17 15:50
---------------	------------------

MOT test number	612230826277
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #8	2017-04-21 14:18
---------------	------------------

MOT test number	279901126179
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Suspension arm rubber bush deteriorated but not resulting in excessive movement o/s/f (2.4.G.2)
---------------	---

MOT #7	2016-02-19 13:31
---------------	------------------

MOT test number	434952637854
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2016-02-19 13:02
---------------	------------------

MOT test number	104729755600
------------------------	--------------

Result	✗ Failed
---------------	----------

Fail	Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
-------------	---

Fail	Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)
-------------	---

MOT #5	2015-02-23 14:19
---------------	------------------

MOT test number	795024555077
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2014-03-17 15:25
---------------	------------------

MOT test number	196396574444
------------------------	--------------

Result	✓ Passed
---------------	----------

**MOT #3** 2013-03-14 10:20**MOT test number** 936433473084**Result** ✓ Passed**MOT #2** 2012-04-04 16:09**MOT test number** 715005392031**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** All tyres cracking**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2011-02-22 08:42**MOT test number** 768413751075**Result** ✓ Passed**Notice** Coolant level low.**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	RO08PYU
Plate since	2024-03-28
Current registration	RO08PYU
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2008-03-17
Last registration	2021-10-20
Complete history	See info



Registration #1	2008-03-17	20 mi
Registration #2	2011-02-22	20.622 mi
Registration #3	2012-04-04	38.300 mi
Registration #4	2013-03-14	41.516 mi
Registration #5	2014-03-17	44.712 mi
Registration #6	2015-02-23	47.703 mi
Registration #7	2016-02-19	50.320 mi
Registration #8	2016-05-20	51.377 mi
Registration #9	2016-05-20	51.377 mi
Registration #10	2016-05-20	51.377 mi
Registration #11	2016-05-20	51.377 mi
Registration #12	2016-05-20	51.377 mi
Registration #13	2016-05-20	51.377 mi
Registration #14	2016-05-20	51.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1827 mm
Height	1413 mm
Length	3620 mm
Wheel base	2448 mm
Kerb weight	887 kg
Max. allowed weight	1265 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	7M75675