



report date: 2024-03-29

General information

Make	FIAT
Model	BRAVO SPORT TJET
Colour	Blue
Year of manufacture	2009
Top speed	132 mph
0 - 60 mph	8.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	150 BHP
Max. torque	206 Nm at 2.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.8 mpg
CO2 emission	165 g/km
CO2 label	G





Internet history

Entry 1	
Date	2022-01-11
Pictures	30
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-03-04
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	26
Total items failed	4

MOT #16	2024-03-02 11:30
MOT test number	959479368491
Result	✓ Passed
Next expiry date	2025-03-04
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #15	2023-03-02 09:40
MOT test number	362557157182
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge slightly around inner edge (5.2.3 (e))
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords around inner wall , quite deeply. (5.2.3 (d) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14**

2023-03-02 08:47

MOT test number

180006016628

Result**✗ Failed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords around inner wall , quite deeply. (5.2.3 (d) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge slightly around inner edge (5.2.3 (e))**Fail** Rear Exhaust system insecure mount broken (6.1.2 (a))**MOT #13**

2022-03-03 13:45

MOT test number

666010271892

Result**✓ Passed****MOT #12**

2022-03-03 09:51

MOT test number

638620938014

Result**✗ Failed****Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #11**

2021-03-05 09:23

MOT test number

248311925599

Result**✓ Passed****Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened nearside , offside (1.1.14 (a) (ii))**Advice** Rear Exhaust mounting defective (6.1.2 (a))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened nearside , offside (1.1.14 (a) (ii))**Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

**MOT #10**

2019-12-02 14:54

MOT test number

459445686388

Result

✓ Passed

Advice Brake fluid close to minimum mark (1.1.10 (d) (ii))**Advice** Front Brake disc worn, but not excessively both side (1.1.14 (a) (i))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #9**

2019-12-02 10:43

MOT test number

233827372508

Result

✗ Failed

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Front Brake disc worn, but not excessively both side (1.1.14 (a) (i))**Fail** Front Windscreen wiper does not clear the windscreen effectively both side (3.4 (b) (ii))**Advice** Brake fluid close to minimum mark (1.1.10 (d) (ii))**MOT #8**

2018-11-20 08:30

MOT test number

612984384344

Result

✓ Passed

Minor Obligatory mirror slightly loose (3.3 (b) (i))**MOT #7**

2018-11-20 08:30

MOT test number

449795530930

Result

✗ Failed

Minor Obligatory mirror slightly loose (3.3 (b) (i))**Pass with rectification** Windscreen washer not working (3.5 (a))

**MOT #6** 2017-11-28 09:44**MOT test number** 570496862586**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2016-11-25 08:45**MOT test number** 417712309213**Result** ✓ Passed**Advice** Both rear tyres perished**MOT #4** 2015-11-26 07:53**MOT test number** 460831831552**Result** ✓ Passed**MOT #3** 2014-11-12 09:33**MOT test number** 427526014432**Result** ✓ Passed**MOT #2** 2013-11-25 09:21**MOT test number** 877649023365**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components**MOT #1** 2012-11-29 09:18**MOT test number** 247994632314**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
4 March 2025

Tax status	Valid until 1 April
Days left	337
MOT expiry date	4 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-11-30
Last registration	2024-03-02
Complete history	See info



Registration #1	2009-11-30	26 mi
Registration #2	2012-11-29	16.079 mi
Registration #3	2013-11-25	20.739 mi
Registration #4	2014-11-12	24.114 mi
Registration #5	2015-11-26	30.546 mi
Registration #6	2016-11-25	36.795 mi
Registration #7	2017-11-28	40.303 mi
Registration #8	2018-11-20	44.258 mi
Registration #9	2018-11-20	44.258 mi
Registration #10	2019-11-20	48.213 mi
Registration #11	2019-11-20	48.213 mi
Registration #12	2019-11-20	48.213 mi
Registration #13	2019-11-20	48.213 mi
Registration #14	2019-11-20	48.213 mi
Registration #15	2019-11-20	48.213 mi
Registration #16	2019-11-20	48.213 mi
Registration #17	2019-11-20	48.213 mi
Registration #18	2019-11-20	48.213 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1792 mm
Height	1498 mm
Length	4336 mm
Wheel base	2600 mm
Kerb weight	1275 kg
Max. allowed weight	1785 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1442510