





report date: 2024-03-29

General information

| Make | FIAT |
|---------------------|-------------------|
| Model | GRAND PUNTO SOUND |
| Colour | Grey |
| Year of manufacture | 2010 |
| Top speed | 103 mph |
| 0 - 60 mph | 13.2 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 77 BHP |
|-------------------------|---------------------|
| Max. torque | 115 Nm at 3.000 rpm |
| Engine capacity | 1.368 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 37.7 mpg |
| Consumption extra urban | 56.5 mpg |
| Consumption combined | 47.9 mpg |
| CO2 emission | 139 g/km |
| CO2 label | E |



CarCheck.co.uk page 1/12



WV10GZK report date: 2024-03-29

Internet history

Entry 2

Date 2023-08-22

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

| Date | 2021-10-06 |
|------|------------|
| | |

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



WV10GZK report date: 2024-03-29

MOT history

| MOT expiry date | 2025-01-12 |
|--------------------|------------|
| MOT pass rate | 44 % |
| MOT passed | 4 |
| Failed MOT tests | 5 |
| Total advice items | 16 |
| Total items failed | 13 |

| MOT #9 | 2024-01-13 12:58 |
|---|-----------------------|
| MOT test number | 693930952778 |
| Result | ✓ Passed |
| Next expiry date | 2025-01-12 |
| Advice Offside Front Suspension arm pin or bush worn but not resulting in exceptush (5.3.4 (a) (i)) | essive movement Rear |
| Advice Oil leak, but not excessive (8.4.1 (a) (i)) | |
| Advice Nearside Front Suspension arm pin or bush worn but not resulting in exbush (5.3.4 (a) (i)) | cessive movement Rear |

| MOT #8 | | 2023-08-10 11:30 |
|------------|--|------------------|
| MOT test n | number | 904526782210 |
| Result | | ✓ Passed |
| Advice | Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii) |) |

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #7 2023-08-09 10:25 **MOT** test number 551652687764 Result × Failed Fail Front Registration plate inscription illegible (0.1 (b)) Fail Nearside Headlamp insecure broken (4.1.1 (c)) Nearside Rear Seat belt retracting mechanism defective (7.1.2 (e)) Fail Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Front suspension quite rusty, subframe, struts, hubs and calipers

MOT #6 2021-10-01 13:59 743759025536 **MOT test number** Result ★ Failed Fail Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii)) Fail Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii)) Rear exhaust deteriorated **Advice Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Fail Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii)) **Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Supplementary restraint system warning lamp indicates a fault (7.1.6 (a)) Fail **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #5 2016-09-21 15:48 484917333792 **MOT** test number Result × Failed **Advice** Bodywork damage **Advice** Front Brake pad(s) wearing thin (3.5.1g) Fail Supplementary Restraint System warning lamp indicates a fault (5.4.2) Advice Items removed from driver's view prior to test **Advice** Nearside Front & both rear tyres perished **Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #4

2014-09-18 13:05

MOT test number

295661264265

Result

✓ Passed

MOT #3

2014-09-17 16:51

MOT test number

689730864289

Result

✓ Fail

Offside Obligatory mirror does not provide a view to the rear (8.1.2b)

MOT #2 2013-10-02 17:08 **MOT** test number 287235673229 Result ✓ Passed **MOT #1** 2013-10-02 16:37 **MOT** test number 826305273280 Result × Failed Offside Rear fog lamp not working (1.3.2b) Fail Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



| Tax status | Valid until 1 July |
|------------------|--------------------|
| Days left | 62 |
| MOT expiry date | 12 January 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Plate since

WV10GZK

report date: 2024-03-29

| Owner history | |
|---|-------------|
| For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report | |
| ********* | |
| | |
| *************************************** | |
| ********** | |
| *************************************** | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this FIAT had different number plates. | |
| Number of plates | |
| | |

More info >

EXPERSE

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 12 |
| First mileage registration | 2010-04-21 |
| Last registration | 2024-01-13 |
| Complete history | See info |



| Registration #1 | 2010-04-21 | 11 mi |
|------------------|------------|-----------|
| Registration #2 | 2013-10-02 | 37.548 mi |
| Registration #3 | 2013-10-02 | 37.548 mi |
| Registration #4 | 2014-09-17 | 38.600 mi |
| Registration #5 | 2014-09-18 | 38.600 mi |
| Registration #6 | 2016-09-21 | 45.180 mi |
| Registration #7 | | 11.777 es |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.777 es |
| Registration #12 | | |

More info >

CarCheck.co.uk page 11/12



WV10GZK report date: 2024-03-29

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 50567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 1687 mm |
|---------------------|---------|
| Height | 1490 mm |
| Length | 4030 mm |
| Wheel base | 2510 mm |
| Kerb weight | 1040 kg |
| Max. allowed weight | 1600 kg |

Additional information

| Fuel delivery | Multi-Point Injection |
|-----------------------------------|-----------------------|
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles CarCheck.co.uk | 2 page 12/12 |