



HJ6IRWE

report date: 2024-03-29

General information

Make	NISSAN
Model	LEAF
Colour	Silver
Year of manufacture	2011
Top speed	90 mph
Gearbox	1 speed automatic

Engine & fuel consumption

Power	107 BHP
Max. torque	254 Nm at 10.500 rpm
Fuel type	Electricity





LABEL UNKNOWN



Internet history

Entry 5

Date	2021-08-09
Pictures	33
Listing price	View report



source: [autotrader.co.uk](#)

Entry 4

Date	2021-07-26
Pictures	33
Listing price	View report



source: [autotrader.co.uk](#)

Entry 3

Date	2021-07-11
Pictures	33
Listing price	View report



source: [autotrader.co.uk](#)

Entry 2


Date	2021-06-30
------	------------

Pictures

33

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

Date


2021-06-16

Pictures

32

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-02-19
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	29
Total items failed	6

MOT #15 2024-02-14 11:48**MOT test number** 307727709206**Result** ✓ Passed**Next expiry date** 2025-02-19**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))**MOT #14** 2024-02-14 09:48**MOT test number** 262082377155**Result** ✗ Failed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**MOT #13** 2023-02-20 15:27**MOT test number** 612903330803**Result** ✓ Passed

**MOT #12** 2022-01-18 10:32**MOT test number** 418057675391**Result** ✓ Passed**MOT #11** 2021-11-08 17:55**MOT test number** 750352334835**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front brake discs corroded on inner face**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Both front headlight lenses slightly deteriorated**MOT #10** 2021-10-27 11:31**MOT test number** 781208388223**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))**Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))**MOT #9** 2020-10-16 14:54**MOT test number** 338779355497**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #8** 2020-10-07 12:19**MOT test number** 113076962942**Result** ✗ Failed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #7** 2019-09-24 15:35**MOT test number** 377868885550**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside front tyre worn on inner edge on 3mm**MOT #6** 2018-09-20 13:56**MOT test number** 307499462127**Result** ✓ Passed**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #5** 2017-10-03 11:37**MOT test number** 286692302345**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit around 2mm, bald on outer edge (4.1.E.1)**Advice** Both rear tyres slightly perished**Advice** Offside Front Tyre worn close to the legal limit around 2mm. (4.1.E.1)

**MOT #4** 2016-09-29 11:37**MOT test number** 110123109310**Result** ✓ Passed**Advice** Both rear tyres starting to perish**MOT #3** 2015-09-22 07:52**MOT test number** 384830317821**Result** ✓ Passed**MOT #2** 2014-09-24 14:43**MOT test number** 496937964212**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Nail in nearside rear tyre**MOT #1** 2014-09-24 14:43**MOT test number** 529247164264**Result** ✗ Failed**Notice** Under-trays fitted obscuring some underside components**Notice** Nail in nearside rear tyre**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
19 February 2025

Tax status	Valid until 1 March
-------------------	---------------------

Days left	306
------------------	-----

MOT expiry date	19 February 2025
------------------------	------------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2011-09-30
Last registration	2024-02-14
Complete history	See info



Registration #1	2011-09-30	29 mi
Registration #2	2014-09-24	14.232 mi
Registration #3	2015-09-22	19.100 mi
Registration #4	2016-09-29	24.615 mi
Registration #5	2017-10-03	30.672 mi
Registration #6	2018-09-20	37.270 mi
Registration #7	2019-09-24	46.525 mi
Registration #8	2020-10-07	52.724 mi
Registration #9	2020-10-16	52.764 mi
Registration #10	2020-10-16	52.764 mi
Registration #11	2020-10-16	52.764 mi
Registration #12	2020-10-16	52.764 mi
Registration #13	2020-10-16	52.764 mi
Registration #14	2020-10-16	52.764 mi
Registration #15	2020-10-16	52.764 mi
Registration #16	2020-10-16	52.764 mi
Registration #17	2020-10-16	52.764 mi
Registration #18	2020-10-16	52.764 mi
Registration #19	2020-10-16	52.764 mi
Registration #20	2020-10-16	52.764 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	83%
Pedestrian	65%
Safety systems	84%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1550 mm
Length	4445 mm
Wheel base	2770 mm
Kerb weight	1525 kg
Max. allowed weight	1965 kg

Additional information

Fuel delivery	Not Applicable
Number of doors	5
Number of seats	5
Number of axles	2

Engine number	10464A
---------------	--------