



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	GOLF TDI SPORT 5 STR
Colour	Blue
Year of manufacture	2009
Top speed	122 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	46.3 mpg
CO2 emission	159 g/km
CO2 label	G






Internet history

Entry 2

Date	2023-05-01
Pictures	20
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

Date	2021-06-12
Pictures	47
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-03-06
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	20
Total items failed	7

MOT #19	2024-02-26 09:58
MOT test number	748237211904
Result	✓ Passed
Next expiry date	2025-03-06
Advice	Front Oil leak, but not excessive from engine (8.4.1 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Front Suspension arm pin or bush worn but not resulting in excessive movement both front (5.3.4 (a) (i))

MOT #18	2023-03-02 14:58
MOT test number	920046122323
Result	✓ Passed
Advice	Suspension arm pin or bush worn but not resulting in excessive movement front both next to subframe cast housing (5.3.4 (a) (i))

**MOT #17**

2023-03-02 09:57

MOT test number

128323707823

Result**✗ Failed****Fail**

Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice

Suspension arm pin or bush worn but not resulting in excessive movement front both next to subframe cast housing (5.3.4 (a) (i))

MOT #16

2022-03-04 11:39

MOT test number

381224426677

Result**✓ Passed****Minor**

Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Minor

Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #15

2021-02-16 16:17

MOT test number

409872846279

Result**✓ Passed****Advice**

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14

2021-02-15 15:02

MOT test number

700947511143

Result**✗ Failed****Fail**

Exhaust emissions likely to be affected by an exhaust leak (8.2.2.1 (b))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13** 2020-02-17 16:12**MOT test number** 778899679941**Result** ✓ Passed**Advice** Minor exhaust gas leak from egr cooler area**Minor** Nearside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))**Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #12** 2019-02-18 16:00**MOT test number** 409662243549**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**MOT #11** 2018-02-12 11:20**MOT test number** 557725686469**Result** ✓ Passed**MOT #10** 2017-03-07 10:40**MOT test number** 442327314639**Result** ✓ Passed**MOT #9** 2016-02-03 17:06**MOT test number** 153907817762**Result** ✓ Passed**Advice** Offside Front Inner Tyre worn close to the legal limit (4.1.E.1)

**MOT #8** 2016-02-03 17:06**MOT test number** 953625610100**Result** ✗ Failed**Advice** Offside Front Inner Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #7** 2015-02-20 11:38**MOT test number** 529741055086**Result** ✓ Passed**MOT #6** 2015-02-17 15:30**MOT test number** 907698645051**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Pass with rectification** Offside Headlamp aim too low (1.8)**MOT #5** 2014-09-04 11:25**MOT test number** 367237544227**Result** ✓ Passed**MOT #4** 2014-09-04 11:20**MOT test number** 879927044215**Result** ✗ Failed**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**MOT #3** 2013-09-05 12:00**MOT test number** 378318943466**Result** ✓ Passed



MOT #2	2012-09-05 10:55
MOT test number	519579442253
Result	✓ Passed
MOT #1	2012-02-29 14:27
MOT test number	205050162098
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
6 March 2025

Tax status	Valid until 1 February
Days left	278
MOT expiry date	6 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner 1	2015-01-01
Owner 2	2015-01-01
Owner 3	2015-01-01
Owner 4	2015-01-01
Owner 5	2015-01-01
Owner 6	2015-01-01

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	AK58WFU
Plate since	2015-01-01
Current registration	AK58WFU
Plate since	2015-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2009-01-26
Last registration	2024-02-26
Complete history	See info



Registration #1	2009-01-26	24 mi
Registration #2	2012-02-29	32.049 mi
Registration #3	2012-09-05	36.815 mi
Registration #4	2013-09-05	44.099 mi
Registration #5	2014-09-04	53.535 mi
Registration #6	2014-09-04	53.535 mi
Registration #7	2015-02-17	57.458 mi
Registration #8	2015-02-20	57.458 mi
Registration #9	2016-02-03	73.817 mi
Registration #10	2016-02-03	73.817 mi
Registration #11	2017-03-07	95.791 mi
Registration #12	2019-05-29	101.277 mi
Registration #13	2019-05-29	101.277 mi
Registration #14	2019-05-29	101.277 mi
Registration #15	2019-05-29	101.277 mi
Registration #16	2019-05-29	101.277 mi
Registration #17	2019-05-29	101.277 mi
Registration #18	2019-05-29	101.277 mi
Registration #19	2019-05-29	101.277 mi
Registration #20	2019-05-29	101.277 mi
Registration #21	2019-05-29	101.277 mi
Registration #22	2024-02-26	101.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1561 kg
Max. allowed weight	2260 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Engine number	BKD C72007