



report date: 2024-03-28

General information

Make	FORD
Model	GALAXY GHIA TDDI
Colour	Green
Year of manufacture	-
Top speed	117 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	310 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	34.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	43.5 mpg







Internet history

Entry 1

Date	2021-06-07
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)





## MOT history

MOT #22

2022-05-20 11:58

MOT test number

878235140860

Result

✓ Passed

Next expiry date

2023-06-07

- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Offside Front Outer Seat belt anchorage prescribed area is corroded but not considered excessive sill (7.1.1 (a) (i))
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Suspension component ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Nearside Seat belt anchorage prescribed area is corroded but not considered excessive sill (7.1.1 (a) (i))
- Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Play in steering rack inner joint(s)
- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

MOT #21

2021-06-08 09:47

MOT test number

512031280222

Result

✓ Passed





<b>MOT #20</b>	2021-06-08 08:53
<b>MOT test number</b>	386124392976
<b>Result</b>	✗ Failed
<b>Fail</b>	Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
<b>MOT #19</b>	2020-07-15 15:35
<b>MOT test number</b>	436958380684
<b>Result</b>	✓ Passed
<b>MOT #18</b>	2019-07-25 10:26
<b>MOT test number</b>	300145401312
<b>Result</b>	✓ Passed
<b>MOT #17</b>	2019-07-25 10:26
<b>MOT test number</b>	929256898082
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))
<b>MOT #16</b>	2018-07-12 15:06
<b>MOT test number</b>	269419790522
<b>Result</b>	✓ Passed
<b>MOT #15</b>	2017-07-06 11:33
<b>MOT test number</b>	502422622269
<b>Result</b>	✓ Passed
<b>MOT #14</b>	2016-07-12 14:59
<b>MOT test number</b>	193416006415
<b>Result</b>	✓ Passed



**MOT #13** 2015-07-07 13:00**MOT test number** 457738585194**Result** ✓ Passed**MOT #12** 2014-07-15 15:50**MOT test number** 498876794145**Result** ✓ Passed

- Notice** O/s/r tyre starting to wear on sides
- Notice** Rear discs show corrosion
- Notice** Front tyres side wear + nearing wear barrs +-3mm

**MOT #11** 2014-07-15 13:28**MOT test number** 265366894481**Result** ✗ Failed

- Notice** Front tyres side wear + nearing wear barrs +-3mm
- Fail** Rear Rear fog lamp not working (1.3.2b)
- Notice** O/s/r tyre starting to wear on sides
- Notice** Rear discs show corrosion

**MOT #10** 2013-07-23 09:02**MOT test number** 275124103256**Result** ✓ Passed

- Notice** Rear discs show corrosion

**MOT #9** 2013-07-22 17:20**MOT test number** 716003003279**Result** ✗ Failed

- Fail** Hazard warning tell tale not working correctly (1.4.B.1e)



**MOT #8** 2012-07-24 13:49**MOT test number** 875366802238**Result** ✓ Passed**MOT #7** 2011-08-02 12:45**MOT test number** 359244911222**Result** ✓ Passed**MOT #6** 2011-08-02 12:45**MOT test number** 738334311267**Result** ✗ Failed**Pass with rectification** Centre Exhaust has a major leak of exhaust gases (7.1.2)**MOT #5** 2010-07-01 13:05**MOT test number** 474802780185**Result** ✓ Passed**Notice** Front inner + rear discs starting to show corrosion**Notice** Front tyres wearing nearing limits + wear bars**MOT #4** 2010-07-01 09:21**MOT test number** 850932280168**Result** ✗ Failed**Fail** Exhaust has a major leak of exhaust gases (7.1.2)**Notice** Front inner + rear discs starting to show corrosion**Fail** Emissions not tested (7.0)**Notice** Front tyres wearing nearing limits + wear bars





MOT #3	2010-06-30 16:41
MOT test number	602781480107
Result	✗ Failed
Fail	Nearside Rear Exhaust has a major leak of exhaust gases (7.1.2)
Notice	Front tyres wearing near wear barr indicators
Notice	Inner front + rear discs starting to show corrososn

MOT #2	2009-07-27 16:57
MOT test number	244588709225
Result	✓ Passed

MOT #1	2008-08-01 15:44
MOT test number	154194418281
Result	✓ Passed





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-28
Current registration	*****
Plate since	2019-06-28

More info >





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX


More info >





Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-06-30
Last registration	2022-05-20
Complete history	<a href="#">See info</a>



Registration #1	2005-06-30	19 mi
Registration #2	2008-08-01	27.049 mi
Registration #3	2009-07-27	36.125 mi
Registration #4	2010-06-30	43.769 mi
Registration #5	2010-07-01	43.771 mi
Registration #6	2010-07-01	43.778 mi
Registration #7	2011-08-02	50.599 mi
Registration #8	2012-07-24	56.721 mi
Registration #9	2013-07-22	63.190 mi
Registration #10	2013-07-23	63.191 mi
Registration #11	2014-07-15	69.166 mi
Registration #12	2014-07-15	69.166 mi
Registration #13	2015-05-20	75.277 mi
Registration #14	2015-05-20	75.277 mi
Registration #15	2015-05-20	75.277 mi
Registration #16	2015-05-20	75.277 mi
Registration #17	2015-05-20	75.277 mi
Registration #18	2015-05-20	75.277 mi
Registration #19	2015-05-20	75.277 mi
Registration #20	2015-05-20	75.277 mi
Registration #21	2015-05-20	75.277 mi
Registration #22	2015-05-20	75.277 mi
Registration #23	2015-05-20	75.277 mi

More info >





Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2142 mm
Height	1759 mm
Length	4641 mm
Wheel base	2835 mm
Kerb weight	1694 kg
Max. allowed weight	2510 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	4S28957