



General information

Make	FORD
Model	FOCUS C-MAX ZETEC
Colour	Blue
Year of manufacture	2006
Top speed	116 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	155 Nm at 4.150 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.8 mpg
CO2 emission	160 g/km
CO2 label	G





Internet history

Entry 2


Date	2023-12-13
Pictures	8



source: g3remarketing.co.uk

Entry 1

Date	2021-09-25
Pictures	20
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-24
MOT pass rate	63 %
MOT passed	15
Failed MOT tests	9
Total advice items	50
Total items failed	14

MOT #24	2023-09-21 11:18
MOT test number	300459921450
Result	✓ Passed
Next expiry date	2024-09-24
Advice	Headlamp has a product on the lens but not seriously reducing light output BOTH (4.1.4 (b))
Advice	UNDERSIDE AND BODY COROSION

MOT #23	2023-09-21 11:18
MOT test number	924819219849
Result	✗ Failed
Pass with rectification	Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Advice	UNDERSIDE AND BODY COROSION
Pass with rectification	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Pass with rectification	Offside Rear Anti-roll bar linkage insecurely attached (5.3.3 (a) (i))
Pass with rectification	Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Pass with rectification	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Headlamp has a product on the lens but not seriously reducing light output BOTH (4.1.4 (b))

**MOT #22** 2022-09-23 13:15**MOT test number** 758840910521**Result** ✓ Passed**Advice** Underside has corrosion**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #21** 2022-09-23 13:15**MOT test number** 851931627075**Result** ✗ Failed**Pass with rectification** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Underside has corrosion**MOT #20** 2021-09-25 08:10**MOT test number** 810437433832**Result** ✓ Passed**MOT #19** 2020-11-06 09:53**MOT test number** 335658285227**Result** ✓ Passed**MOT #18** 2019-11-08 15:46**MOT test number** 342151624813**Result** ✓ Passed**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

**MOT #17** 2019-11-08 11:37**MOT test number** 516393914070**Result** ✗ Failed**DANGEROUS** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))**DANGEROUS** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))**MOT #16** 2018-11-16 13:46**MOT test number** 187689545795**Result** ✓ Passed**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #15** 2018-11-16 09:39**MOT test number** 243036716734**Result** ✗ Failed**Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MAJOR** Offside Front Suspension arm pin or bush excessively worn rear (5.3.4 (a) (i))**Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Nearside Front Suspension arm pin or bush excessively worn rear (5.3.4 (a) (i))

**MOT #14** 2017-11-10 09:25**MOT test number** 141374503341**Result** ✓ Passed**MOT #13** 2016-11-25 12:07**MOT test number** 510435779799**Result** ✓ Passed**MOT #12** 2015-11-13 09:45**MOT test number** 617091227001**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #11** 2014-11-21 10:31**MOT test number** 827615724338**Result** ✓ Passed**MOT #10** 2013-11-29 09:49**MOT test number** 365623933372**Result** ✓ Passed**Advice** Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**Notice** Near side rear tyre wearing on edge**Notice** Nail in offside rear tyre**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**Notice** Off side rear tyre wearing on edge



MOT #9 2013-11-29 09:49

MOT test number 479973033324

Result ✗ Failed

- Advice** Offside Front Suspension arm has slight play in a pin/bush (2.4.G.2)
- Notice** Off side rear tyre wearing on edge
- Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)
- Advice** Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)
- Notice** Near side rear tyre wearing on edge
- Notice** Nail in offside rear tyre
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #8 2012-11-16 11:17

MOT test number 925871922391

Result ✓ Passed

- Notice** O/s/r tyre starting to crack on inner and outer tyre walls
- Notice** Slight noise from o/s/r wheel bearing
- Notice** Nail in offside rear tyre
- Notice** Stone chip on passengers side of front screen

**MOT #7** 2012-11-16 11:17**MOT test number** 669281822329**Result** ✗ Failed**Notice** O/s/r tyre starting to crack on inner and outer tyre walls**Notice** Slight noise from o/s/r wheel bearing**Pass with rectification** Offside Front Headlamp not working on dipped beam (1.7.5a)**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Nail in offside rear tyre**Notice** Stone chip on passangers side of front screen**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #6** 2011-11-18 09:48**MOT test number** 598832521300**Result** ✓ Passed**Notice** Both front tyres worn bold on inner edges .**MOT #5** 2011-11-18 09:48**MOT test number** 675022621335**Result** ✗ Failed**Notice** Both front tyres worn bold on inner edges .**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #4** 2010-11-27 09:57**MOT test number** 422611730398**Result** ✓ Passed



MOT #3	2010-11-26 14:43
MOT test number	651100930395
Result	✗ Failed
Fail	Parking brake: efficiency below requirements (3.7.B.7)
Fail	Offside rear parking brake recording little or no effort (3.7.B.6a)

MOT #2	2009-11-27 12:10
MOT test number	482191439322
Result	✓ Passed

MOT #1	2009-11-27 10:02
MOT test number	622811739324
Result	✗ Failed
Fail	Brakes imbalanced across an axle (3.7.B.5b)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
24 September 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	24 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-28
Current registration	*****
Plate since	2019-06-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2006-12-06
Last registration	2023-09-21
Complete history	See info



Registration #1	2006-12-06	25 mi
Registration #2	2009-11-27	27.171 mi
Registration #3	2009-11-27	27.171 mi
Registration #4	2010-11-26	39.503 mi
Registration #5	2010-11-27	39.503 mi
Registration #6	2011-11-18	52.321 mi
Registration #7	2012-11-16	65.657 mi
Registration #8	2013-11-29	77.622 mi
Registration #9	2014-11-21	90.243 mi
Registration #10	2015-11-13	104.163 mi
Registration #11	2016-11-25	118.879 mi
Registration #12	2017-11-10	132.567 mi
Registration #13	2018-11-20	146.255 mi
Registration #14	2019-11-20	159.943 mi
Registration #15	2020-11-20	173.631 mi
Registration #16	2021-11-20	187.319 mi
Registration #17	2022-11-20	201.007 mi
Registration #18	2023-09-21	214.695 mi
Registration #19	2023-09-21	214.695 mi
Registration #20	2023-09-21	214.695 mi
Registration #21	2023-09-21	214.695 mi
Registration #22	2023-09-21	214.695 mi
Registration #23	2023-09-21	214.695 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1825 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1371 kg
Max. allowed weight	1870 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	6S66240