



HONDA




report date: 2024-03-28

General information

Make	HONDA
Model	ACCORD VTEC EXECUTIVE
Colour	Blue
Year of manufacture	2004
Top speed	133 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	153 BHP
Max. torque	190 Nm at 4.500 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.4 mpg
Consumption extra urban	41.5 mpg
Consumption combined	31.7 mpg
CO2 emission	211 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-06-17
Pictures	1
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-01-19
MOT pass rate	58 %
MOT passed	18
Failed MOT tests	13
Total advice items	80
Total items failed	14

MOT #31	2024-01-17 13:54
MOT test number	463516718706
Result	✓ Passed
Next expiry date	2025-01-19

MOT #30	2024-01-11 15:20
MOT test number	676248816361
Result	✗ Failed
MAJOR Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
MAJOR Nearside Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))	
MAJOR Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))	
MAJOR Exhaust has a major leak of exhaust gases (6.1.2 (a))	
MAJOR Offside Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))	

MOT #29	2023-01-20 10:41
MOT test number	223866005691
Result	✓ Passed
Advice	Fuel Pipe/s corroded



MOT #28	2023-01-19 14:35
MOT test number	526577491547
Result	✗ Failed
Advice	Fuel Pipe/s corroded
MAJOR	Nearside Front Upper Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

MOT #27	2022-01-06 13:45
MOT test number	473048550022
Result	✓ Passed
Advice	Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Fuel Pipe/s corroded

MOT #26	2022-01-04 13:59
MOT test number	714588066580
Result	✗ Failed
Advice	Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Fuel Pipe/s corroded
MAJOR	Headlamp not working on dipped beam (4.1.1 (a) (ii))
Advice	Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
MAJOR	Offside Upper Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**MOT #25**

2021-01-08 11:01

MOT test number

881036228668

Result

✓ Passed

Advice Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #24**

2021-01-08 11:01

MOT test number

916394170093

Result

✗ Failed

Advice Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Pass with rectification** Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Pass with rectification** Windscreen wiper not working (3.4 (a))**Advice** Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #23**

2019-12-23 14:44

MOT test number

951094290199

Result

✓ Passed

Advice Fuel Pipe/s corroded**Advice** Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Brake hose slightly deteriorated (1.1.12 (b) (ii))

**MOT #22**

2019-12-20 14:54

MOT test number

885151844729

Result**✗ Failed**

- Advice** Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Brake hose slightly deteriorated (1.1.12 (b) (ii))
- MAJOR** Nearside Front Upper Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Fuel Pipe/s corroded
- Advice** Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #21

2019-01-10 16:43

MOT test number

800387673451

Result**✓ Passed**

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Sill covers fitted
- Advice** Nearside Front Upper Suspension component ball joint has slight play (5.3.4 (a) (i))

**MOT #20** 2019-01-08 14:56**MOT test number** 839243094260**Result** ✗ Failed**MAJOR** Nearside Headlamp aim so that beam "kick up" is not visible on the screen (4.1.2 (a))**Advice** Sill covers fitted**MAJOR** Nearside Headlamp light intensity severely reduced (4.1.4 (a))**MAJOR** Front Exhaust has a major leak of exhaust gases (6.1.2 (a))**DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MAJOR** Offside Rear Service brake excessively fluctuating (1.2.1 (e))**Advice** Nearside Front Upper Suspension component ball joint has slight play (5.3.4 (a) (i))**MAJOR** Offside Headlamp aim so that beam "kick up" is not visible on the screen (4.1.2 (a))**MAJOR** Offside Headlamp light intensity severely reduced (4.1.4 (a))**DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**MAJOR** Offside Rear Service brake excessively binding (1.2.1 (f))**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #19** 2018-01-08 17:24**MOT test number** 684532946166**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)



MOT #18 2018-01-08 09:06

MOT test number 994422272441

Result ✗ Failed

- Fail

Nearside Headlamp aim so that beam "kick up" is not visible on the screen (1.8.B.1)
- Advice

Front Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail

Nearside Front Anti-roll bar linkage insecure (2.4.G.1)
- Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #17 2017-01-04 14:35

MOT test number 764719668813

Result ✓ Passed

- Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice

Front Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #16**

2017-01-04 09:06

MOT test number

961963162353

Result

✗ Failed

Fail Nearside Front Suspension arm rubber mounting deteriorated resulting in excessive movement (2.4.G.2)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Offside Front Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)

Advice Front Exhaust has a minor leak of exhaust gases (7.1.2)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Offside Front Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)

MOT #15

2016-01-07 09:20

MOT test number

125554172307

Result

✓ Passed

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Front Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Front Lower Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)

Advice Front Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #14

2015-01-08 09:12

MOT test number

238458405018

Result

✓ Passed

**MOT #13** 2015-01-07 10:44**MOT test number** 477127905004**Result** ✗ Failed**Fail** Offside Rear Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Suspension arm rubber mounting deteriorated resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #12** 2014-01-08 14:31**MOT test number** 866368504093**Result** ✓ Passed**Advice** Offside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**Advice** Offside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #11** 2014-01-08 09:09**MOT test number** 958448404051**Result** ✗ Failed**Advice** Offside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**Advice** Offside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Offside Rear rear brake binding (3.7.B.1)**MOT #10** 2013-01-10 09:28**MOT test number** 806190713085**Result** ✓ Passed

**MOT #9** 2013-01-10 09:28**MOT test number** 915150013025**Result** ✗ Failed**Pass with rectification** Nearside rear brake binding (3.7.B.1)**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #8** 2012-01-06 15:41**MOT test number** 225516902075**Result** ✓ Passed**MOT #7** 2012-01-06 09:01**MOT test number** 297436202049**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm rubber mounting deteriorated resulting in excessive movement (2.4.G.2)**MOT #6** 2011-01-17 12:27**MOT test number** 899777811096**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2011-01-17 09:12**MOT test number** 476057011069**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #4	2010-01-19 09:50
MOT test number	731079110070
Result	✓ Passed
MOT #3	2009-07-22 16:29
MOT test number	251983309259
Result	✓ Passed
MOT #2	2008-07-21 16:19
MOT test number	791343208270
Result	✓ Passed
MOT #1	2007-07-18 15:15
MOT test number	294999597100
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
19 January 2025

Tax status	Valid until 1 June
Days left	33
MOT expiry date	19 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history


Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	32
First mileage registration	2004-07-30
Last registration	2024-01-17
Complete history	See info



Registration #1	2004-07-30	9 mi
Registration #2	2007-07-18	8.053 mi
Registration #3	2008-07-21	15.731 mi
Registration #4	2009-07-22	21.316 mi
Registration #5	2010-01-19	25.352 mi
Registration #6	2011-01-17	32.768 mi
Registration #7	2011-01-17	32.768 mi
Registration #8	2012-01-06	38.569 mi
Registration #9	2012-01-06	38.569 mi
Registration #10	2013-01-10	43.352 mi
Registration #11	2014-01-08	47.723 mi
Registration #12	2014-01-08	47.723 mi
Registration #13	2015-01-07	51.911 mi
Registration #14	2015-01-08	51.911 mi
Registration #15	2016-01-07	56.202 mi
Registration #16	2017-01-04	60.227 mi
Registration #17	2018-01-01	65.227 mi
Registration #18	2018-01-01	65.227 mi
Registration #19	2018-01-01	65.227 mi
Registration #20	2018-01-01	65.227 mi
Registration #21	2018-01-01	65.227 mi
Registration #22	2018-01-01	65.227 mi
Registration #23	2018-01-01	65.227 mi
Registration #24	2018-01-01	65.227 mi
Registration #25	2018-01-01	65.227 mi
Registration #26	2018-01-01	65.227 mi

Registration #27	2025-25-25	25,252,442
Registration #28	2025-25-25	25,252,442
Registration #29	2025-25-25	25,252,442
Registration #30	2025-25-25	25,252,442
Registration #31	2025-25-25	25,252,442
Registration #32	2025-25-25	25,252,442

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1760 mm
Height	1470 mm
Length	4750 mm
Wheel base	2670 mm
Kerb weight	1434 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Engine number	K20A62500166