



BVIIYTA

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TRANSPORTER T28 TDI P/V
Colour	White
Year of manufacture	2011
Top speed	98 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.1 mpg
Consumption extra urban	44.8 mpg
Consumption combined	37.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-02-06
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-10-31
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	11
Total items failed	6

MOT #13	2023-10-26 09:25
MOT test number	619322221969
Result	✓ Passed
Next expiry date	2024-10-31

MOT #12	2022-10-10 14:16
MOT test number	621700342913
Result	✓ Passed

MOT #11	2021-10-26 07:54
MOT test number	336535117420
Result	✓ Passed
Advice	Offside Front Road wheel fractured at bridge over valve (5.2.2 (a))

MOT #10	2020-10-13 14:46
MOT test number	912568234204
Result	✓ Passed

**MOT #9** 2019-10-16 08:31**MOT test number** 997530801073**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**MOT #8** 2019-10-15 13:24**MOT test number** 917626656554**Result** ✗ Failed**Fail** Front Service brake imbalanced across an axle (1.2.1 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #7** 2018-10-08 12:13**MOT test number** 437297017404**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #6** 2017-11-01 09:27**MOT test number** 441117278704**Result** ✓ Passed**MOT #5** 2016-10-28 10:51**MOT test number** 310547479961**Result** ✓ Passed**MOT #4** 2015-10-09 11:53**MOT test number** 377675750474**Result** ✓ Passed**MOT #3** 2014-10-06 15:38**MOT test number** 917809774264**Result** ✓ Passed**MOT #2** 2013-10-29 13:54**MOT test number** 665792003323**Result** ✓ Passed**MOT #1** 2013-10-25 13:18**MOT test number** 979128093295**Result** ✗ Failed**Fail** Offside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Fail** Nearside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)



Tax & MOT check

✓
Taxed

Tax due:
1 October 2024

✓
MOT

Expires:
31 October 2024

Tax status		Valid until 1 October
Days left		155
MOT expiry date		31 October 2024
Full MOT history		See MOT history



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 BV11YTA
Plate since	2019-03-29
Current registration	 BV11YTA
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-03-28
Last registration	2023-10-26
Complete history	See info



Registration #1	2011-03-28	14 mi
Registration #2	2013-10-25	59.981 mi
Registration #3	2013-10-29	59.982 mi
Registration #4	2014-10-06	69.831 mi
Registration #5	2015-10-09	78.112 mi
Registration #6	2016-10-28	86.296 mi
Registration #7	2017-11-01	94.124 mi
Registration #8	2018-10-08	94.647 mi
Registration #9	2019-10-26	95.277 mi
Registration #10	2020-10-26	95.277 mi
Registration #11	2021-10-26	95.277 mi
Registration #12	2022-10-26	95.277 mi
Registration #13	2023-10-26	95.277 mi
Registration #14	2024-03-29	95.277 mi
Registration #15	2024-03-29	95.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1904 mm
Height	1990 mm
Length	4892 mm
Wheel base	3000 mm
Kerb weight	1851 kg
Max. allowed weight	2800 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of seats	3

Number of axles	2
Engine number	CAA 216870