



report date: 2024-03-28

General information

Make	FIAT
Model	PUNTO POP PLUS
Colour	White
Year of manufacture	2017
Top speed	97 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.8 mpg
Consumption extra urban	65.7 mpg
Consumption combined	53.3 mpg
CO2 emission	124 g/km
CO2 label	D





Internet history

Entry 2

Date 2021-02-05

Pictures 26

Listing price [View report](#)



source: yesauto.com

Entry 1

Date 2021-01-29

Pictures 10

Listing price [View report](#)



source: autoonline.co.uk



MOT history

MOT expiry date	2024-06-22
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	13
Total items failed	7

MOT #5	2023-06-23 15:04
MOT test number	528130662690
Result	✓ Passed
Next expiry date	2024-06-22
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #4**

2023-06-22 15:23

MOT test number

624366581373

Result**✗ Failed**

- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3

2022-06-07 15:00

MOT test number

588005281607

Result**✓ Passed**

- Advice** Nearside Front Tyre slightly damaged/cracking or perishing tyre cracking on outer edge, perishing on outer wall (5.2.3 (d) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing cracking on outer edge (5.2.3 (d) (ii))

**MOT #2** 2022-06-06 15:16**MOT test number** 368856242491**Result** ✗ Failed

Advice Nearside Front Tyre slightly damaged/cracking or perishing tyre cracking on outer edge, perishing on outer wall (5.2.3 (d) (ii))

Fail Offside Rear Tyre has a tear, caused by separation or partial failure of its structure perished cracking on outer edge (5.2.3 (d) (ii))

Pass with rectification Offside Front Position lamp not working side lamp (4.2.1 (a) (ii))

Advice Offside Front Tyre slightly damaged/cracking or perishing cracking on outer edge (5.2.3 (d) (ii))

Fail Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure perishing (5.2.3 (d) (ii))

MOT #1 2020-12-23 15:14**MOT test number** 188439823732**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
22 June 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	22 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-12-20
Last registration	2023-06-23
Complete history	See info



Registration #1	2017-12-20	13 mi
Registration #2	2020-12-23	18.094 mi
Registration #3	2022-06-23	25.277 mi
Registration #4	2023-06-23	25.277 mi
Registration #5	2023-06-23	25.277 mi
Registration #6	2023-06-23	25.277 mi
Registration #7	2023-06-23	25.277 mi
Registration #8	2023-06-23	25.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1030 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1856787