



report date: 2024-03-29

General information

Make	AUDI
Model	TT TFSI
Colour	Black
Year of manufacture	2008
Top speed	149 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	200 BHP
Max. torque	280 Nm at 1.800 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg
CO2 emission	183 g/km
CO2 label	I








Internet history

Entry 3



Date	2021-07-11
Pictures	17
Listing price	View report



source: [autotrader.co.uk](#)

Entry 2


Date	2021-06-30
Pictures	17
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-04
Pictures	13
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-07-30
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	28
Total items failed	4

MOT #16	2023-07-31 13:44
MOT test number	558771178410
Result	✓ Passed
Next expiry date	2024-07-30

MOT #15	2022-07-28 12:44
MOT test number	970766582565
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Central Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Service brake grabbing slightly (1.2.1 (c))

MOT #14	2021-10-07 12:53
MOT test number	490950634206
Result	✓ Passed

MOT #13	2021-01-18 10:07
MOT test number	654623465337
Result	✓ Passed

**MOT #12**

2019-05-23 12:36

MOT test number

769685199525

Result

✓ Passed

- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- Advice** Both rear tyre valve stems perished and cracked
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #11

2019-05-22 12:30

MOT test number

413228106494

Result

✗ Failed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Both rear tyre valve stems perished and cracked
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #10** 2018-05-21 13:09**MOT test number** 709958313021**Result** ✓ Passed**MOT #9** 2018-05-21 11:14**MOT test number** 105442000121**Result** ✗ Failed**Fail** Brake fluid contaminated (1.8 (a))**MOT #8** 2017-04-26 13:43**MOT test number** 995125007774**Result** ✓ Passed**MOT #7** 2016-02-03 09:23**MOT test number** 634924726605**Result** ✓ Passed**MOT #6** 2015-02-11 11:51**MOT test number** 156242945459**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** Plastic sills fitted**MOT #5** 2014-02-11 10:10**MOT test number** 395462444005**Result** ✓ Passed

**MOT #4**

2013-02-25 11:15

MOT test number

937516053001

Result

✓ Passed

Advice Offside Rear Shock absorber has a slightly reduced damping effect (2.7.5)**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Rear Shock absorber has a slightly reduced damping effect (2.7.5)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #3**

2012-03-13 07:48

MOT test number

218003472054

Result

✓ Passed

MOT #2

2012-03-13 07:48

MOT test number

879003972063

Result

✗ Failed

Pass with rectification Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #1**

2011-03-22 11:26

MOT test number

785751081040

Result

✓ Passed

Notice Nearside rear tyre worn on the inside edge**Notice** Both the front tyres are worn on the inside edges



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
30 July 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	30 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-




Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-04-18
Last registration	2023-07-31
Complete history	See info



Registration #1	2008-04-18	10 mi
Registration #2	2011-03-22	20.594 mi
Registration #3	2012-03-13	32.747 mi
Registration #4	2013-02-25	36.809 mi
Registration #5	2014-02-11	41.613 mi
Registration #6	2015-02-11	46.275 mi
Registration #7	2016-02-03	49.264 mi
Registration #8	2017-04-26	57.690 mi
Registration #9	2018-05-21	68.266 mi
Registration #10	2018-05-21	68.266 mi
Registration #11	2019-05-21	75.277 mi
Registration #12	2020-05-21	82.288 mi
Registration #13	2021-05-21	89.299 mi
Registration #14	2022-05-21	96.310 mi
Registration #15	2023-05-21	103.321 mi
Registration #16	2024-05-21	110.332 mi
Registration #17	2025-05-21	117.343 mi
Registration #18	2026-05-21	124.354 mi
Registration #19	2027-05-21	131.365 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1842 mm
Height	1352 mm
Length	4178 mm
Wheel base	2468 mm
Kerb weight	1260 kg
Max. allowed weight	1660 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	BWA 230608