





### General information

Make	VOLKSWAGEN
Model	PASSAT TDI SE
Colour	Silver
Year of manufacture	2007
Top speed	126 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed automatic

### Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.4 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.2 mpg
CO2 emission	174 g/km
CO2 label	Н







# Internet history

Entry 1 Date

Pictures


2021-05-23

31

Listing price

View report









# MOT history

MOT expiry date	2025-01-16
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	7
Total items failed	7

MOT #18	2024-01-11 12:35
MOT test number	333808426205
Result	🗸 Passed
Next expiry date	2025-01-16
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deterio	rated (6.1.7 (g) (i))

MOT #17	2023-01-12 12:01
MOT test number	902187479403
Result	✓ Passed
Minor Nearside Front Outer Drive shaft joint constant velocity boot severely	deteriorated (6.1.7 (g) (i))

MOT #16	2023-01-12 10:02
MOT test number	320877622128
Result	🗙 Failed
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Advice Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))	
Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))	
Fail Exhaust emissions exceed manufacturer's specified limit limit 1.00tested 1.48	(8.2.2.2 (a))





MOT #15	2022-01-17 13:42
MOT test number	635364636534
Result	✓ Passed
MOT #14	2022-01-13 11:17
MOT test number	835144776841
Result	× Failed
Fail Nearside Side repeater not working (4.4.1 (a) (ii))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Offside Front Seat belt buckle damaged (7.1.2 (d))	
FailOffside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevent(5.3.4 (b) (ii))	ts the ingress of dirt
Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	

МОТ #13	2021-01-16 16:16
MOT test number	843334326727
Result	✓ Passed

MOT #12	2021-01-16 10:27
MOT test number	862597864706
Result	🗙 Failed

**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 215/55r16 (5.2.3 (d) (i))

MOT #11	2019-09-26 13:22
MOT test number	858158399042
Result	✓ Passed
MOT #10	2019-07-23 07:31
MOT test number	235843783711
Result	✓ Passed





МОТ #9	2018-09-07 16:31
MOT test number	714345278030
Result	✓ Passed
MOT #8	2017-09-01 09:43
MOT test number	635917887039
Result	✓ Passed
MOT #7	2016-08-18 14:05
MOT test number	529311189203
Result	✓ Passed
МОТ #6	2015-09-03 14:09
MOT test number	614102223500
Result	✓ Passed
MOT #5	2014-09-10 09:50
MOT test number	498743154210
Result	✓ Passed
MOT #4	2013-08-30 16:25
MOT test number	345582043266
Result	✓ Passed
МОТ #3	2012-08-31 12:17
MOT test number	268794042279
Result	✓ Passed
MOT #2	2011-08-25 17:21
MOT test number	538077531209
Result	✓ Passed





MOT #1	2010-08-27 10:58
MOT test number	954579330256
Result	✓ Passed





Tax & MOT check

✓ Taxed	✓ MOT
Tax due: 1 May 2024	<b>Expires:</b> 16 January 2025
Tax status	Valid until 1 May
Days left	1
MOT expiry date	16 January 2025
Full MOT history	See MOT history

# Tax calculation

Vehicle class	49
Band	н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-





### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLE
Date	
Date	OLE
Category	AM
Туре	

#### Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10 700

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

**********	
********	
and the second	
***********	
*********	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-09-11
Last registration	2024-01-11
Complete history	<u>See info</u>



Registration #1	2007-09-11	8 mi
Registration #2	2010-08-27	25.568 mi
Registration #3	2011-08-25	33.583 mi
Registration #4	2012-08-31	40.688 mi
Registration #5	2013-08-30	48.517 mi
Registration #6	2014-09-10	56.484 mi
Registration #7	2015-09-03	63.443 mi
Registration #8	2016-08-18	69.012 mi
Registration #9	2017-09-01	72.371 mi
Registration #10	2018-09-07	74.755 mi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		01.777 est
Registration #19		11.777 mi
Registration #20		11.117 mi

More info  $\rightarrow$ 





### Car features

S0225	Air conditioning
\$0295	
S0482	
S0501	
\$0566	
\$0567	
S0569	

# Safety ratings

**NCAP** rating

Video

see crash video



#### Dimensions & weight Width 1820 mm Height 1517 mm Length 4774 mm Wheel base 2709 mm Kerb weight 1738 kg Max. allowed weight 2170 kg Additional information Fuel tank capacity 70 I **Fuel delivery Direct Injection** Number of doors 5

Number of seats	5
Number of axles	2
Engine number	BKP 259788