





report date: 2024-03-28

General information

Make	RENAULT
Model	MEGANE EXTREME II 16V 100
Colour	Green
Year of manufacture	2008
Top speed	114 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	127 Nm at 3.750 rpm
Engine capacity	1.390 сс
Cylinders	4
Fuel type	Petrol
Consumption city	30.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	40.9 mpg
CO2 emission	165 g/km
CO2 label	G



CarCheck.co.uk page 1/15



report date: 2024-03-28

Internet history

Entry 1

Date 2021-02-04

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/15



report date: 2024-03-28

MOT history

MOT expiry date	2022-03-24
MOT pass rate	58 %
MOT passed	11
Failed MOT tests	8
Total advice items	27
Total items failed	20

MOT #19	2021-02-26 15:24
MOT test number	492625995355
Result	✓ Passed
Minor Central Front Upper Windscreen damaged but not adversely affecting drive b (3.2 (a) (i))	2022-03-24 r's view stone chip zone
Advice Nearside Front Play in steering rack inner joint(s)	

MOT #18	2021-02-25 08:31	
MOT test number	830402164707	
Result	X Failed	
Minor Offside Rear Registration plate lamp inoperative in the case of multiple (4.7.1 (b) (i))	lamps or light sources	
Advice Nearside Front Play in steering rack inner joint(s)		
Fail Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))		
Minor Central Front Upper Windscreen damaged but not adversely affecting driver's view stone chip zone b (3.2 (a) (i))		
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))		
Fail Front Headlamp aim projected beam image is obviously incorrect both from	nt dipped beams (4.1.2 (c))	

CarCheck.co.uk page 3/15



Advice

Play in steering rack inner joint(s)

AF08HSY

report date: 2024-03-28

MOT #17

MOT test number

Result

Minor

Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b)

2020-03-23 15:53 **MOT #16 MOT** test number 895095669388 Result × Failed Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii)) Fail **Advice** Play in steering rack inner joint(s) Headlamp aim not tested dip beam not working (4.1.2 (b)) Fail Fail Nearside Front Position lamp not working (4.2.1 (a) (ii)) Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) Fail Offside Headlamp not working on dipped beam (4.1.1 (a) (ii)) Fail Nearside Obligatory mirror missing (3.3 (a))

MOT test number

Result

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor

(i))

Advice

Nearside Rear Service brake binding but not excessively (1.2.1 (f))


Advice

Front top mounts bearing stiff

CarCheck.co.uk page 4/15



report date: 2024-03-28



MOT #13		2018-03-23 13:34
MOT test	number	932643688782
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit 2mm tread (4.1.E.1)	
Advice	Both front tyres heavily perishing/cracking	
Advice	Nearside Front Tyre worn close to the legal limit 2mm tread (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit 3mm tread (4.1.E.1)	

CarCheck.co.uk page 5/15



report date: 2024-03-28

MOT #12 2018-03-23 13:13 **MOT test number** 335178091618 Result **★** Failed **Advice** Offside Front Tyre worn close to the legal limit 2mm tread (4.1.E.1) Nearside Front Front position lamp(s) not working (1.1.A.3b) Fail Advice Nearside Front Tyre worn close to the legal limit 2mm tread (4.1.E.1) Advice Offside Rear Tyre worn close to the legal limit 3mm tread (4.1.E.1) Advice Both front tyres heavily perishing/cracking Fail Nearside Front Headlamp not working on dipped beam (1.7.5a)

MOT #11	2017-03-16 14:35
MOT test number	642707536284
Result	✓ Passed
MOT #10	2017-03-16 13:30
MOT test number	298949560783
Result	× Failed
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	

MOT #9	2016-03-01 10:32
MOT test number	152108029985
Result	✓ Passed

CarCheck.co.uk page 6/15



MOT test number

AF08HSY

report date: 2024-03-28

159869364078

MOT test number

640776647555

Result

Pass with rectification | Nearside Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)

Pass with rectification | Offside Headlamp not working on dipped beam (1.7.5a)

Pass with rectification | Nearside Rear Direction indicator adversely affected by the operation of another lamp (1.4.A.2h)

 MOT #7
 2015-03-24 15:07

 MOT test number
 888823385003

 Result
 ✓ Passed

 MOT #6
 2015-03-24 12:59

 MOT test number
 316233985095

 Result
 X Failed

Offside Rear Direction indicator adversely affected by the operation of another lamp (1.4.A.2h)

MOT #5

2014-03-10 11:11

MOT #4
2013-03-06 15:31

MOT test number
128305863431

Result
✓ Passed

Notice Play in steering rack inner joint(s)

CarCheck.co.uk page 7/15



AF08HSY report date: 2024-03-28

MOT #3 2013-03-05 15:45

MOT test number 145084163055

Result × Failed

Notice Play in steering rack inner joint(s)

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #2 2012-02-20 09:04

MOT test number 739591752064

Result ✓ Passed

MOT #1 2011-02-23 09:49

MOT test number 369304251016

CarCheck.co.uk page 8/15



report date: 2024-03-28

Tax & MOT check



Tax expired: 31 December 2021

MOT Expired: 24 March 2022

Tax statusExpired at 31 December 2021Days left850 days too lateMOT expiry date24 March 2022Full MOT historySee MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 9/15



report date: 2024-03-28

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-28

	Owner	history
--	-------	---------

C Wile History	
For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
MARKET STATE OF THE STATE OF TH	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	NK NE
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 12/15



report date: 2024-03-28

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 13/15



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-03-18
Last registration	2021-02-26
Complete history	See info



Registration #1	2008-03-18	19 mi
Registration #2	2011-02-23	28.708 mi
Registration #3	2012-02-20	40.427 mi
Registration #4	2013-03-05	54.933 mi
Registration #5	2013-03-06	54.933 mi
Registration #6	2014-03-10	58.449 mi
Registration #7	2015-03-24	63.299 mi
Registration #8	2015-03-24	63.299 mi
Registration #9	2016-03-01	66.718 mi
Registration #10	2016-03-01	66.718 mi
Registration #11	2017-03-16	71.145 mi
Registration #12		71.777 es
Registration #13		71.777 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		71.777 es
Registration #17		11.777 es
Registration #18		71.777 es
Registration #19		11.777 mi
Registration #20		71.777 es
Registration #21		11.177 es

More info >

CarCheck.co.uk page 14/15



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2026 mm
Height	1458 mm
Length	4209 mm
Wheel base	2625 mm
Kerb weight	1165 kg
Max. allowed weight	1715 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 15

Number of axles 2

Engine number D033611