





report date: 2024-03-28

General information

Make	LAND ROVER
Model	FREELANDER SD4 HSE LUXURY
Colour	Green
Year of manufacture	2013
Top speed	118 mph
0 - 100 km/h	11.2 seconds
0 - 60 mph	8.7 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	110 kW / 150 HP / 190 BHP
Max. torque	420 Nm at 1.750 rpm
Engine capacity	2.179 сс
Cylinders	4
Fuel type	Diesel
Consumption city	32.5 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.4 mpg
CO2 emission	185 g/km
CO2 label	I



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-02-01

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



OY63XVA

report date: 2024-03-28

MOT history

MOT expiry date	2024-06-30
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	12
Total items failed	7

MOT #10	2023-06-16 09:21
MOT test number	164343924015
Result	✓ Passed
Next expiry date	2024-06-30

MOT #9	2023-06-16 07:57
MOT test number	761390522375
Result	X Failed
Fail Horn not working (7.7 (a))	

MOT #8	2022-06-28 12:56
MOT test number	904940432225
Result	✓ Passed

MOT #7	2021-07-01 10:01
MOT test number	340470805557
Result	✓ Passed

MOT #6	2021-06-30 14:50
MOT test number	789809036226
Result	X Failed
Fail Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))	

CarCheck.co.uk page 3/12



OY63XVA

report date: 2024-03-28

MOT #5 2019-11-12 16:14

MOT test number 311914023147

MOT #4 2019-11-12 10:29

MOT test number 974824572352

Result × Failed

Fail Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))

Fail Nearside Front Road wheel fixing missing (5.2.1 (a) (i))

Minor Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Fail Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))

Fail Offside Front Road wheel fixing missing (5.2.1 (a) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened lipped (1.1.14 (a) (ii))

MOT #3 2018-09-22 11:02

MOT test number 684180779952

Result \(\sqrt{Passed} \)

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2 2017-09-26 13:58

MOT test number 193932589773

Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)

Advice Offside Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 4/12



OY63XVA

report date: 2024-03-28

MOT #1 2016-10-06 09:19

MOT test number 454557636092

MOT test	number	434337030092
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Rear Brake pad(s) wearing thin both (3.5.1g)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	30 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	T
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category

Type

Damage 2

Date

Category

Type



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner	history
OWITEL	HISLULY

For how long did the current and previous owner(s) have this LAND ROVER? How many or ROVER have? Check it in the premium report and see all owner registrations. Download to	

	More info >
Plate changes	
See in this check if this LAND ROVER had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	Zalis UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-10-14
Last registration	2023-06-16
Complete history	See info



Registration #1	2013-10-14	21 mi
Registration #2	2016-10-06	35.571 mi
Registration #3	2017-09-26	51.102 mi
Registration #4	2018-09-22	67.550 mi
Registration #5	2019-11-12	75.038 mi
Registration #6	2019-11-12	75.038 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es

More info >

CarCheck.co.uk page 11/12



Safety ratings

NCAP rating	****

Video <u>see crash video</u>



Dimensions & weight

Width	2180 mm
Height	1740 mm
Length	4500 mm
Wheel base	2660 mm
Kerb weight	1770 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	68 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	DZ784152302224DT

CarCheck.co.uk page 12/12