





report date: 2024-03-29

General information

Make	MERCEDES
Model	C C200 K SE
Colour	Silver
Year of manufacture	2002
Top speed	144 mph
0 - 60 mph	9.4 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	163 BHP
Max. torque	240 Nm at 3.000 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.2 mpg
Consumption extra urban	44.1 mpg
Consumption combined	32.5 mpg
CO2 emission	209 g/km
CO2 label	K



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-02-02

Pictures 9

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-04-27
MOT pass rate	100 %
MOT passed	18
Failed MOT tests	0
Total advice items	29
Total items failed	0

MOT #18	2024-04-17 11:00
MOT test number	216057964486
Result	✓ Passed
Next expiry date	2025-04-27
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Offside Rear Nail in tyre	

MOT #17		2023-04-24 11:06
MOT test	number	442811497309
Result		✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Offside Front Wheel bearing has slight play (5.1.3 (a) (i))	
Advice	Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))	

MOT #16		2022-04-28 12:19
MOT test	number	623799003948
Result		✓ Passed
Advice	Tyre slightly damaged/cracking or perishing all slightly cracking (5.2.3 (d) (ii))	
Advice	Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))	

CarCheck.co.uk page 3/13



K200GLR

report date: 2024-03-29

MOT #15 2021-04-28 13:13

MOT test number 763304388989

MOT #14 2019-08-16 10:18

MOT test number 221088647817

Result

Passed

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #13 2018-08-29 10:02

MOT test number 413077820833

Result \(\sqrt{Passed} \)

Advice Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #12 2017-08-25 08:58

MOT test number 408528056398

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 4/13



MOT #11 2016-08-19 11:10

MOT test number 815036507678

Advice Offside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Front Inner Suspension arm rubber bush deteriorated but not resulting in excessive movement camber arm bush (2.4.G.2)

Advice Nearside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Front Inner Suspension arm rubber bush deteriorated but not resulting in excessive movement camber arm bush (2.4.G.2)

MOT #10 2015-09-01 14:17

MOT test number 448392425182

Result
✓ Passed

MOT #9 2014-08-28 09:02

MOT test number 109350444271

Result \(\sqrt{Passed} \)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Notice Engine covers fitted obscuring some components in the engine bay

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Notice Under-trays fitted obscuring some underside components

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Notice Wipres gone hard but clean ok

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive

movement (2.4.G.2)

MOT #8 2013-08-28 12:01

MOT test number 435520243222

Result

Passed

Notice Under-trays fitted obscuring some underside components

CarCheck.co.uk page 5/13



MOT #7 2012-08-21 12:22

MOT test number 306134732298

Notice Under-trays fitted obscuring some underside components

MOT #6 2011-08-22 11:00

MOT test number 946444831292

Result \sqrt{Passed}

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2010-08-18 12:50

MOT test number 312580830291

Result ✓ Passed

MOT #4 2009-08-12 11:55

MOT test number 641524629227

Result \rightarrow Passed

MOT #3 2008-08-11 12:29

MOT test number 294404928224

Result ✓ Passed

MOT #2 2007-08-14 12:46

MOT test number 171766127222

MOT #1 2006-08-11 11:21

MOT test number 183533626283

Result

Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 November
Days left	185
MOT expiry date	27 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1


Date
Category
Type

Damage 2

Date

Category

Type



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

Owner history	
For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downlo <u>here</u> .	

	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	NK UK
Plate since	m.o.o
Current registration	OK OK
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at info	

Contact info


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2002-09-06
Last registration	2024-04-17
Complete history	See info



Registration #1	2002-09-06	16 mi
Registration #2	2006-08-11	9.246 mi
Registration #3	2007-08-14	10.722 mi
Registration #4	2008-08-11	12.115 mi
Registration #5	2009-08-12	13.555 mi
Registration #6	2010-08-18	14.966 mi
Registration #7	2011-08-22	15.935 mi
Registration #8	2012-08-21	17.264 mi
Registration #9	2013-08-28	17.768 mi
Registration #10	2014-08-28	18.115 mi
Registration #11		9.79 es
Registration #12		11.777 es
Registration #13		9.79 es
Registration #14		11.777 es
Registration #15		9.79 es
Registration #16		11.777 es
Registration #17		9.79 es
Registration #18		71.777 es
Registration #19		11.777 es
Registration #20		11.777 au

More info >

CarCheck.co.uk page 12/13



Dimensions & weight

Width	1728 mm
Height	1406 mm
Length	4343 mm
Wheel base	2715 mm
Kerb weight	2715 kg

Additional information

Fuel tank capacity	62 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2
Engine number	27194030058410

CarCheck.co.uk page 13/13