



PEUGEOT

HJ050HB

report date: 2024-03-29

General information

Make	PEUGEOT
Model	206 SPORT HDI (90BHP)
Colour	Black
Year of manufacture	-
Top speed	111 mph
0 - 60 mph	13.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	205 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	65.7 mpg
Consumption combined	54.3 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-12
Pictures	5
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #22	2021-08-23 08:48
MOT test number	583319393990
Result	✓ Passed
Next expiry date	2022-09-15

MOT #21	2021-08-20 08:54
MOT test number	364499040090
Result	✗ Failed

Fail Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))

MOT #20	2020-09-16 09:28
MOT test number	705204041151
Result	✓ Passed

Advice Brake pipe corroded, covered in grease or other material all (1.1.11 (c))

Advice Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

MOT #19	2020-09-15 10:32
MOT test number	497549409889
Result	✗ Failed

Fail Exhaust particulate filter missing where one was fitted as standard (8.2.2.1 (a))

Advice Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

Fail Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

Advice Brake pipe corroded, covered in grease or other material all (1.1.11 (c))

**MOT #18** 2019-10-22 11:21**MOT test number** 773935757131**Result** ✓ Passed**Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Front Service brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**Advice** Offside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #17** 2018-10-17 14:03**MOT test number** 762131775089**Result** ✓ Passed**MOT #16** 2017-10-17 08:37**MOT test number** 170931218990**Result** ✓ Passed**MOT #15** 2017-10-11 10:21**MOT test number** 764024630352**Result** ✗ Failed**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #14** 2016-10-13 13:56**MOT test number** 455977213087**Result** ✓ Passed

**MOT #13** 2015-12-29 11:47**MOT test number** 415501779568**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit outer edge warn (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit outer edge warn (4.1.E.1)**MOT #12** 2015-12-16 17:18**MOT test number** 711174574494**Result** ✗ Failed**Fail** Offside Rear Radius arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front wheel bearing noisy**Fail** Nearside Rear Radius arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Fail** Rear Exhaust system not adequately supported (7.1.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #11** 2014-12-10 12:22**MOT test number** 805744644318**Result** ✓ Passed**Notice** Rear silencer deteriorated**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #10** 2013-07-03 10:09**MOT test number** 398274883134**Result** ✓ Passed

- Notice** Rear exhaust box outer casing corroded
- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Under-trays fitted obscuring some underside components

MOT #9 2013-07-03 10:09**MOT test number** 508314083147**Result** ✗ Failed

- Notice** Rear exhaust box outer casing corroded
- Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Under-trays fitted obscuring some underside components

MOT #8 2012-06-27 10:52**MOT test number** 588919872111**Result** ✓ Passed**MOT #7** 2011-06-24 10:47**MOT test number** 205875771196**Result** ✓ Passed**MOT #6** 2010-06-30 16:32**MOT test number** 521831380155**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2010-06-30 11:48**MOT test number** 440991580165**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)**MOT #4** 2009-03-27 11:34**MOT test number** 843926389068**Result** ✓ Passed**Advice** Front brake disc slightly pitted (3.5.1h)**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Slight perishing noted in NSR tyre side-wall. No visible cords**MOT #3** 2008-03-12 08:27**MOT test number** 131912878097**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2008-02-11 15:52**MOT test number** 291172048044**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #12008-02-11 13:00

MOT test number321592948034

ResultX Failed

Pass with rectificationNearside Headlamp aim too low (1.8)

FailNearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)

AdviceOffside Front Tyre worn close to the legal limit (4.1.E.1)

Pass with rectificationOffside Headlamp aim too low (1.8)

FailExhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)

NoticeChild seat fitted not allowing full inspection of adult belt



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-03-01
Last registration	2021-08-23
Complete history	See info



Registration #1	2005-03-01	20 mi
Registration #2	2008-02-11	36.767 mi
Registration #3	2008-02-11	36.773 mi
Registration #4	2008-03-12	37.604 mi
Registration #5	2009-03-27	42.539 mi
Registration #6	2010-06-30	45.890 mi
Registration #7	2010-06-30	45.890 mi
Registration #8	2011-06-24	49.717 mi
Registration #9	2012-06-27	52.773 mi
Registration #10	2013-07-03	54.536 mi
Registration #11	2014-12-10	58.662 mi
Registration #12	2015-12-16	63.996 mi
Registration #13	2016-06-20	65.277 mi
Registration #14	2016-06-20	65.277 mi
Registration #15	2016-06-20	65.277 mi
Registration #16	2016-06-20	65.277 mi
Registration #17	2016-06-20	65.277 mi
Registration #18	2016-06-20	65.277 mi
Registration #19	2016-06-20	65.277 mi
Registration #20	2016-06-20	65.277 mi
Registration #21	2016-06-20	65.277 mi
Registration #22	2016-06-20	65.277 mi
Registration #23	2016-06-20	65.277 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1746 mm
Height	1512 mm
Length	4202 mm
Wheel base	2608 mm
Kerb weight	1260 kg
Max. allowed weight	1760 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	DYTG3003186