



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	PASSAT HIGHLINE TDI DSG
Colour	Grey
Year of manufacture	2010
Top speed	128 mph
0 - 60 mph	8.6 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 2.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	158 g/km
CO2 label	G





## MOT history

MOT expiry date	2025-03-18
MOT pass rate	100 %
MOT passed	11
Failed MOT tests	0
Total advice items	25
Total items failed	0

MOT #11	2024-03-16 11:32
MOT test number	941892030033
Result	✓ Passed
Next expiry date	2025-03-18
Advice	Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #10	2023-03-06 16:51
MOT test number	532970050122
Result	✓ Passed
Advice	Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Lower Oil leak, but not excessive under tray fitted (8.4.1 (a) (i))

MOT #9	2022-03-15 16:01
MOT test number	615751450316
Result	✓ Passed
Advice	Front Inner Suspension arm pin or bush worn but not resulting in excessive movement BOTH SIDE BUSH (5.3.4 (a) (i))
Advice	Rear AXLE CORRODED
Advice	Offside Front Inner Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security SILL JACKING POINT (6.2.2 (d) (i))

**MOT #8** 2021-03-19 12:50**MOT test number** 809502733421**Result** ✓ Passed**Advice** Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #7** 2020-01-22 12:34**MOT test number** 318860278825**Result** ✓ Passed**MOT #6** 2018-11-20 14:56**MOT test number** 671920113576**Result** ✓ Passed**Advice** Nearside Front Pad sensor harness broken**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #5** 2017-12-12 10:32**MOT test number** 333056208411**Result** ✓ Passed**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Advice** Offside Rear coil spring corroded (2.4.C.1b)

**MOT #4** 2016-11-15 10:52**MOT test number** 311003864149**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit inner edge (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit inner edge (4.1.E.1)**MOT #3** 2015-12-15 14:48**MOT test number** 755998109214**Result** ✓ Passed**MOT #2** 2014-12-30 13:41**MOT test number** 346404364350**Result** ✓ Passed**Notice** Inner faces of front brake discs poor = 2k max**MOT #1** 2014-01-17 15:29**MOT test number** 538317714009**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

X

Untaxed

Tax expired:  
23 April 2024

✓

MOT

Expires:  
18 March 2025

Tax status	Expired at 23 April 2024
Days left	7 days too late
MOT expiry date	18 March 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>DE10NNG</b>
Plate since	2019-06-29
Current registration	 <b>DE10NNG</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2010-04-01
Last registration	2024-03-16
Complete history	<a href="#">See info</a>



Registration #1	2010-04-01	25 mi
Registration #2	2014-01-17	40.874 mi
Registration #3	2014-12-30	50.694 mi
Registration #4	2015-12-15	60.831 mi
Registration #5	2016-11-15	69.683 mi
Registration #6	2017-12-12	77.227 mi
Registration #7	2019-05-29	95.277 mi
Registration #8	2019-05-29	95.277 mi
Registration #9	2019-05-29	95.277 mi
Registration #10	2019-05-29	95.277 mi
Registration #11	2019-05-29	95.277 mi
Registration #12	2019-05-29	95.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1472 mm
Length	4765 mm
Wheel base	2709 mm
Kerb weight	1476 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	CBA 755957