





report date: 2024-03-29

#### General information

Make	TOYOTA
Model	CARINA CD
Colour	Silver
Year of manufacture	1996
Top speed	116 mph
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	113 BHP
Max. torque	144 Nm at 5.100 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol



CarCheck.co.uk page 1/15



report date: 2024-03-29

### Internet history

#### Entry 1

Date	2021-02-05
Pictures	1
Listing price	View report



source: autoonline.co.uk

CarCheck.co.uk page 2/15



report date: 2024-03-29

MOT history	Μ	OT	h	is	to	rv
-------------	---	----	---	----	----	----

MOT expiry date	2021-10-20
MOT pass rate	71 %
MOT passed	15
Failed MOT tests	6
Total advice items	35
Total items failed	15

MOT #21	2020-10-21 18:53
MOT test number	163761630690
Result	✓ Passed
Next expiry date	2021-10-20

MOT #20		2019-10-05 12:32
MOT test	number	184874857794
Result		✓ Passed
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))	
Advice	Steering box has seepage (2.1.1 (e) (i))	
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Offside Rear Shock absorbers light misting of oil or has limited damping effect	(5.3.2 (b))
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))	
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Nearside Rear Shock absorbers light misting of oil or has limited damping effe	ect (5.3.2 (b))

CarCheck.co.uk page 3/15



report date: 2024-03-29

**MOT #19** 2019-10-03 11:23 **MOT** test number 374162882229 Result **X** Failed **Advice** Offside Front Coil spring corroded (5.3.1 (b) (i)) **Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i)) Fail Service brake efficiency less than 50% of the required value (1.2.2 (a) (ii)) Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) **Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b)) Minor Nearside Front Windscreen wiper blade defective (3.4 (b) (i)) **Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i)) **Advice** Steering box has seepage (2.1.1 (e) (i)) **Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i)) Fail Front Brake pipe at imminent risk of failure or fracture to rear (1.1.11 (a)) **Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii)) Fail **Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b)) Minor Offside Front Windscreen wiper blade defective (3.4 (b) (i))

MOT #18	2018-09-24 09:45
MOT test number	707449491788
Result	✓ Passed
MOT #17	2017-09-25 09:29
MOT test number	650346150264
Result	✓ Passed

CarCheck.co.uk page 4/15



report date: 2024-03-29

мот #	16	2016-10-04 09:29
MOT te	st number	567427633449
Result		✓ Passed
MOT #	15	2015-09-24 11:42
MOT te	st number	186821588386
Result		✓ Passed
MOT #	14	2015-09-24 10:16
MOT te	st number	476376141654
Result		<b>×</b> Failed
Fail	Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)	
Fail	Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.	D.3)
Fail	Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)	
Fail	Exhaust emissions hydrocarbon content after 2nd fast idle excessive (7.3.D.3)	
Fail	Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	

MOT #13	2014-09-23 13:47
MOT test number	515296064277
Result	<b>✓</b> Passed
Notice Oil leak	

CarCheck.co.uk page 5/15



Fail

N438RCN

report date: 2024-03-29

MOT test number

607551964270

Result

Fail Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)

Notice Oil leak

Fail Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)

Fail Exhaust emissions hydrocarbon content after 2nd fast idle excessive (7.3.D.3)

Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)

MOT #11

MOT test number

428689863208

Result

Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)

Advice Nearside Front Brake pipe slightly corroded (3.6.B.2c)

Notice Mil lamp illuminated

MOT #10

MOT test number

Result

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

 MOT #9
 2011-09-30 11:27

 MOT test number
 459133071294

 Result
 ✓ Passed

CarCheck.co.uk page 6/15



report date: 2024-03-29

MOT #8	2011-09-29 11:00
MOT test number	339002871287
Result	<b>x</b> Failed
Fail Brakes imbalanced across an axle (3.7.B.5b)	

MOT #7	2010-10-01 11:27
MOT test number	490844270235
Result	✓ Passed
MOT #6	2010-10-01 10:52
MOT test number	784304670267
Result	<b>×</b> Failed
Fail Brakes imbalanced across an axle (3.7.B.5b)	

MOT #5	2009-10-06 12:21
MOT test number	264549779247
Result	✓ Passed
MOT #4	2009-10-06 10:04
MOT test number	174149379276
Result	<b>X</b> Failed
Fail Offside Rear Brake pipe excessively corroded (3.6.B.2c)	
Advice Nearside Rear Brake pipe slightly corroded (3.6.B.2c)	

MOT #3	2008-09-23 13:27
MOT test number	102397868213
Result	<b>✓</b> Passed

CarCheck.co.uk page 7/15



report date: 2024-03-29

MOT test number

Result

Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)

Notice O/s/f mud flap loose

Advice Nearside Front Brake pipe slightly corroded (3.6.B.2c)

Engine management light on

MOT #1		2006-09-26 15:18
MOT test	number	512089166240
Result		<b>✓</b> Passed
Advice	Nearside Front Brake pipe slightly corroded (3.6.B.2c)	
Advice	Offside Outer Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Exhaust has a minor leak of exhaust gases (7.1.2)	
Advice	Offside Front Brake pipe slightly corroded (3.6.B.2c)	

CarCheck.co.uk page 8/15



report date: 2024-03-29

#### Tax & MOT check



X MOT

Expired: 20 October 2021

Tax status Expired at 27 August 2020

Days left 1341 days too late

MOT expiry date 20 October 2021

Full MOT history See MOT history

CarCheck.co.uk page 9/15



report date: 2024-03-29

#### Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-29

# Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full	
THE STATE OF THE S	
***************************************	
**************	
********	
***************************************	
THE STREET STREET	
	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	
Current registration	NK SIX
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 12/15



report date: 2024-03-29

#### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 13/15



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	1996-01-27
Last registration	2020-10-21
Complete history	See info



Registration #1	1996-01-27	17 mi
Registration #2	2006-09-26	25.474 mi
Registration #3	2007-09-25	27.745 mi
Registration #4	2008-09-23	29.534 mi
Registration #5	2009-10-06	32.657 mi
Registration #6	2009-10-06	32.657 mi
Registration #7	2010-10-01	35.378 mi
Registration #8	2010-10-01	35.378 mi
Registration #9	2011-09-29	37.632 mi
Registration #10	2011-09-30	37.633 mi
Devictor #11	2012-09-27	39.924 mi
Registration #11	2012-09-27	
Registration #12	2013-09-26	42.113 mi
Registration #12	2013-09-26	42.113 mi
Registration #12 Registration #13	2013-09-26	42.113 mi
Registration #12 Registration #13 Registration #14	2013-09-26	42.113 mi
Registration #12 Registration #13 Registration #14 Registration #15	2013-09-26	42.113 mi
Registration #12 Registration #13 Registration #14 Registration #15 Registration #16	2013-09-26	42.113 mi
Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17	2013-09-26	42.113 mi
Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18	2013-09-26	42.113 mi
Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19	2013-09-26	42.113 mi
Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20	2013-09-26	42.113 mi

More info >

CarCheck.co.uk page 14/15



report date: 2024-03-29

#### Car features

S0225	Air conditioning
50295	
50482	
60501	
60566	
60567	
50569	

#### Additional information

Number of axles	2
Engine number	4AL227625

CarCheck.co.uk page 15/15