



TOYOTA

**RN550DW**

report date: 2024-03-28

General information

Make	TOYOTA
Model	RAV-4 D-4D XT-R
Colour	Grey
Year of manufacture	2006
Top speed	106 mph
0 - 60 mph	12.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	250 Nm at 1.800 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	46.3 mpg
Consumption combined	39.8 mpg
CO2 emission	190 g/km
CO2 label	J






Internet history

Entry 1

Date	2022-01-13
Pictures	14
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2025-01-10
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	38
Total items failed	3

MOT #21	2023-12-12 10:28
MOT test number	908873622526
Result	✓ Passed
Next expiry date	2025-01-10

MOT #20	2023-01-11 14:52
MOT test number	886738234388
Result	✓ Passed

MOT #19	2023-01-05 16:54
MOT test number	654799134152
Result	✗ Failed

**MAJOR** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))

**MAJOR** Offside Front Driver's view of the road through the swept area of the windscreen significantly affected by an obstruction (3.1 (a) (ii))

**MAJOR** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**MAJOR** Nearside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))

**Minor** Trailer electrical socket insecure (4.10 (a) (i))

**MOT #18**

2022-01-11 12:07

**MOT test number**

313060639180

**Result**

✓ Passed

**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Headlamp lens slightly defective (4.1.1 (b) (i))**MOT #17**

2021-12-30 10:06

**MOT test number**

995090871512

**Result**

✗ Failed

**DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MAJOR** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))**MAJOR** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Minor** Headlamp lens slightly defective (4.1.1 (b) (i))**MOT #16**

2021-01-02 12:15

**MOT test number**

902505616262

**Result**

✓ Passed

**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Rear Passenger seat(s) missing at time of test



<b>MOT #15</b>	2019-06-01 11:11
<b>MOT test number</b>	637595521687
<b>Result</b>	✓ Passed
<b>Minor</b>	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
<b>Advice</b>	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

<b>MOT #14</b>	2019-05-31 14:15
<b>MOT test number</b>	451644634302
<b>Result</b>	✗ Failed
<b>Advice</b>	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
<b>DANGEROUS</b>	Fuel system component leaking excessively or a risk of fire (6.1.3 (b) (ii))
<b>Minor</b>	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
<b>MAJOR</b>	Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

<b>MOT #13</b>	2018-06-12 15:29
<b>MOT test number</b>	703478835731
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
<b>Advice</b>	Many various underside components corroded but not weakened, brake pipes, ferrules, sub-frame etc
<b>Advice</b>	Fluid leak, but not excessive (8.4.1 (a) (i))
<b>Advice</b>	Both front tyres bald on inner edge

<b>MOT #12</b>	2017-06-07 14:06
<b>MOT test number</b>	396594002750
<b>Result</b>	✓ Passed
<b>Advice</b>	Suspension bushes slight deterioration, rear shock bushes cracking, flexi brake hoses slight rusting to ferrules
<b>Advice</b>	Front tyres slightly worn on edges

**MOT #11** 2016-06-06 12:56**MOT test number** 783673673772**Result** ✓ Passed**MOT #10** 2015-06-24 14:14**MOT test number** 215795075481**Result** ✓ Passed**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside Rear Shock absorber has a slightly worn bush (2.7.4)**Notice** Side to side movement in steering rack**MOT #9** 2015-06-24 10:22**MOT test number** 119315875110**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar has excessive play in a ball joint (2.4.G.2)**Advice** Nearside Rear Shock absorber has a slightly worn bush (2.7.4)**Notice** Side to side movement in steering rack**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #8** 2014-06-16 16:00**MOT test number** 279517764165**Result** ✓ Passed**MOT #7** 2013-07-29 14:56**MOT test number** 896360113250**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2013-07-29 14:56**MOT test number** 449600913246**Result** ✗ Failed**Pass with rectification** Offside Front Steering rack insecure (2.2.B.1a)**Pass with rectification** Offside Front Lower Steering locking device insecure (2.2.C.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2012-08-06 09:59**MOT test number** 607559212256**Result** ✓ Passed**MOT #4** 2011-09-27 15:04**MOT test number** 217960571235**Result** ✓ Passed**MOT #3** 2010-09-30 09:08**MOT test number** 392433970486**Result** ✓ Passed**MOT #2** 2009-09-17 11:23**MOT test number** 983500169258**Result** ✓ Passed**MOT #1** 2008-10-06 17:03**MOT test number** 873840088246**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 July 2024

✓  
**MOT**

**Expires:**  
10 January 2025

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	64
<b>MOT expiry date</b>	10 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	J
<b>Single payment (12 months)</b>	£ 365,00,-
<b>Single six month payment</b>	£ 200,75,-
<b>Total payable by 12 monthly instalments</b>	£ 383,25,-





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-01-25
Last registration	2023-12-12
Complete history	<a href="#">See info</a>



Registration #1	2006-01-25	9 mi
Registration #2	2008-10-06	24.489 mi
Registration #3	2009-09-17	34.311 mi
Registration #4	2010-09-30	43.921 mi
Registration #5	2011-09-27	53.713 mi
Registration #6	2012-08-06	58.263 mi
Registration #7	2013-07-29	67.943 mi
Registration #8	2014-06-16	77.085 mi
Registration #9	2015-06-24	84.088 mi
Registration #10	2015-06-24	84.088 mi
Registration #11	2016-06-06	90.933 mi
Registration #12	2016-06-06	90.933 mi
Registration #13	2016-06-06	90.933 mi
Registration #14	2016-06-06	90.933 mi
Registration #15	2016-06-06	90.933 mi
Registration #16	2016-06-06	90.933 mi
Registration #17	2016-06-06	90.933 mi
Registration #18	2016-06-06	90.933 mi
Registration #19	2016-06-06	90.933 mi
Registration #20	2016-06-06	90.933 mi
Registration #21	2016-06-06	90.933 mi
Registration #22	2016-06-06	90.933 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1785 mm
Height	1710 mm
Length	4260 mm
Wheel base	2490 mm
Kerb weight	1490 kg
Max. allowed weight	1930 kg

Additional information

Fuel tank capacity	57 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	1CD0535962