



report date: 2024-03-29

General information

| | |
|---------------------|----------------|
| Make | VAUXHALL |
| Model | ZAFIRA SRI NAV |
| Colour | White |
| Year of manufacture | 2018 |
| Top speed | 122 mph |
| 0 - 60 mph | 10.2 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 138 BHP |
| Max. torque | 200 Nm at 1.850 rpm |
| Engine capacity | 1.364 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 33.2 mpg |
| Consumption extra urban | 49.6 mpg |
| Consumption combined | 41.5 mpg |
| CO2 emission | 156 g/km |
| CO2 label | G |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-09-04 |
| Pictures | 27 |
| Listing price | View report |



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-10-10 |
| MOT pass rate | 100 % |
| MOT passed | 4 |
| Failed MOT tests | 0 |
| Total advice items | 4 |
| Total items failed | 0 |

MOT #4 2023-10-06 09:33

MOT test number 630867531137

Result ✓ Passed

Next expiry date 2024-10-10

Advice Offside Front Tyre slightly damaged/cracking or perishing 3 mm tread depth (5.2.3 (d) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing 3 mm tread depth (5.2.3 (d) (ii))

MOT #3 2022-10-10 09:31

MOT test number 882851112165

Result ✓ Passed**Advice** Offside Front Tyre slightly damaged/cracking or perishing Outer side wall (5.2.3 (d) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing Outer side wall (5.2.3 (d) (ii))

MOT #2 2021-10-11 16:23

MOT test number 823983017779

Result ✓ Passed

MOT #1 2021-04-06 11:30

MOT test number 239990819680

Result ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 March 2025

✓
MOT

Expires:
10 October 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 March |
| Days left | 305 |
| MOT expiry date | 10 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--------------------------------------|------------|
| Vehicle class | 48 |
| Band | I |
| First licence fee (12 months) | £ 645,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | LV18DVA |
| Plate since | 2019-03-29 |
| Current registration | LV18DVA |
| Plate since | 2019-03-29 |

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 6 |
| First mileage registration | 2018-05-09 |
| Last registration | 2023-10-06 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2018-05-09 | 12 mi |
| Registration #2 | 2021-04-06 | 19.701 mi |
| Registration #3 | 2023-10-06 | 25.277 mi |
| Registration #4 | 2023-10-06 | 25.277 mi |
| Registration #5 | 2023-10-06 | 25.277 mi |
| Registration #6 | 2023-10-06 | 25.277 mi |

More info >



Safety ratings

| | |
|-------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2099 mm |
| Height | 1685 mm |
| Length | 4658 mm |
| Wheel base | 2760 mm |
| Kerb weight | 1538 kg |
| Max. allowed weight | 2310 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 58 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 7 |
| Engine number | B14NET -19TA0727LUJ |