



YAI3YAH

report date: 2024-03-28

General information

Make	VOLVO
Model	V60 D3 ES
Colour	Red
Year of manufacture	2013
Top speed	127 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	350 Nm at 2.250 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history



Entry 2

Date	2022-11-14
Pictures	0
Listing price	View report

source: [carcraft.co.uk](#)

Entry 1

Date	2021-09-24
Pictures	18
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-02-21
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	8
Total items failed	3

MOT #12	2024-02-08 09:29
MOT test number	531488194052
Result	✓ Passed
Next expiry date	2025-02-21

MOT #11	2023-02-22 12:11
MOT test number	238750277823
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #10	2022-10-25 11:39
MOT test number	871849075827
Result	✓ Passed

MOT #9	2021-10-04 08:43
MOT test number	636715894144
Result	✓ Passed

MOT #8	2021-04-06 13:38
MOT test number	895935594254
Result	✓ Passed

**MOT #7** 2021-04-06 08:05**MOT test number** 457462292128**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #6** 2020-04-17 08:21**MOT test number** 113833082302**Result** ✓ Passed**MOT #5** 2019-04-08 15:15**MOT test number** 556655159634**Result** ✓ Passed**Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4** 2019-04-08 10:03**MOT test number** 178180260223**Result** ✗ Failed**Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #3** 2018-04-17 09:22**MOT test number** 615495100946**Result** ✓ Passed



MOT #2	2017-04-06 09:30
MOT test number	143087687194
Result	✓ Passed
Advice	Offside Rear tyre on 3mm
Advice	Front pads reg soon.

MOT #1	2016-04-07 08:07
MOT test number	712863237801
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 February 2025

✓
MOT

Expires:
21 February 2025

Tax status	Valid until 1 February
Days left	278
MOT expiry date	21 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-04-22
Last registration	2024-02-08
Complete history	See info



Registration #1	2013-04-22	29 mi
Registration #2	2016-04-07	34.333 mi
Registration #3	2017-04-06	46.792 mi
Registration #4	2018-04-17	64.832 mi
Registration #5	2019-04-08	79.834 mi
Registration #6	2019-04-08	79.834 mi
Registration #7	2020-04-17	94.497 mi
Registration #8	2021-04-06	103.174 mi
Registration #9	2022-04-06	111.851 mi
Registration #10	2023-04-06	120.528 mi
Registration #11	2023-04-06	120.528 mi
Registration #12	2023-04-06	120.528 mi
Registration #13	2023-04-06	120.528 mi
Registration #14	2023-04-06	120.528 mi
Registration #15	2024-02-08	129.205 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	see crash video



Dimensions & weight

Width	2097 mm
Height	1484 mm
Length	4628 mm
Wheel base	2776 mm
Kerb weight	1632 kg
Max. allowed weight	2180 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	1263673
---------------	---------