



report date: 2024-03-28

General information

Make	MAZDA
Model	6 TS
Colour	Red
Year of manufacture	-
Top speed	126 mph
0 - 60 mph	11.1 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	147 BHP
Max. torque	184 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	25.5 mpg
Consumption extra urban	49.6 mpg
Consumption combined	36.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-10
Pictures	8
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT #15</b>	2021-06-11 07:53
<b>MOT test number</b>	162957704834
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-06-10

<b>MOT #14</b>	2021-04-29 11:43
<b>MOT test number</b>	354744478352
<b>Result</b>	✓ Passed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both. (1.1.14 (a) (ii))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect damp. (5.3.2 (b))
- Advice** Underside of vehicle heavily corroded.
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing heavily cracking / worn. (5.2.3 (d) (ii))
- Advice** Bonnet primary retaining device slightly deteriorated catch stiff. (3.1 (c))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Items removed from driver's view prior to test

<b>MOT #13</b>	2020-03-19 11:06
<b>MOT test number</b>	400490636635
<b>Result</b>	✓ Passed

<b>MOT #12</b>	2019-03-09 16:07
<b>MOT test number</b>	279648728168
<b>Result</b>	✓ Passed

- Advice** Slight damage to front bumper

**MOT #11**

2018-03-09 17:02

**MOT test number**

863367746156

**Result**

✓ Passed

**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Front Brake pad(s) wearing thin very low (3.5.1g)**Advice** Offside Rear Tyre worn close to the legal limit and cracked and perished (4.1.E.1)**Advice** General rusty under car**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Tyre worn close to the legal limit and cracked and perished (4.1.E.1)**MOT #10**

2017-03-07 15:05

**MOT test number**

553612600064

**Result**

✓ Passed

**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #9**

2017-02-28 15:07

**MOT test number**

582129611427

**Result**

✗ Failed

**Advice** Rear discs corroding/ lipped**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Advice** Nearside rear brake fluctuating, but not excessively (3.7.B.3)

**MOT #8**

2016-03-03 14:00

**MOT test number**

987365702472

**Result**

✓ Passed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Rear discs corroding
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #7**

2016-02-25 13:09

**MOT test number**

594918941288

**Result**

✗ Failed

- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Fail** Offside Front Anti-roll bar linkage damaged and seriously weakened (2.4.G.1)
- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Rear discs corroding

**MOT #6**

2015-03-02 11:40

**MOT test number**

196371365052

**Result**

✓ Passed

**MOT #5**

2015-03-02 11:40

**MOT test number**

189581365473

**Result**

✗ Failed

- Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)

**MOT #4** 2014-02-27 15:56**MOT test number** 376418954009**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #3** 2013-02-27 09:45**MOT test number** 927458653081**Result** ✓ Passed**Notice** Both front tyres wearing on edges**Notice** Chip in screen**MOT #2** 2012-03-02 14:51**MOT test number** 158782162002**Result** ✓ Passed**Notice** Both front tyres wearing on edges**Advice** Offside Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #1** 2011-02-22 16:16**MOT test number** 205173751018**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** Nearside-offside front tyre's worn on outer-inner edge's**Notice** Child seat fitted not allowing full inspection of adult belt



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2019-01-01
Current registration	<b>XXXXXX</b>
Plate since	2019-01-01

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX XXXX
Date of agreement	XXXXXXXXXX XXXX
Agreement type	XXXXXXXXXX XXXX
Agreement term	XXXXXXXXXX XXXX
Agreement number	XXXXXXXXXX XXXX
Contact info	XXXXXXXXXX XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-03-18
Last registration	2021-06-11
Complete history	<a href="#">See info</a>



Registration #1	2008-03-18	18 mi
Registration #2	2011-02-22	16.625 mi
Registration #3	2012-03-02	21.488 mi
Registration #4	2013-02-27	24.219 mi
Registration #5	2014-02-27	29.431 mi
Registration #6	2015-03-02	33.863 mi
Registration #7	2016-02-25	37.957 mi
Registration #8	2016-03-03	38.051 mi
Registration #9	2016-03-03	38.051 mi
Registration #10	2016-03-03	38.051 mi
Registration #11	2016-03-03	38.051 mi
Registration #12	2016-03-03	38.051 mi
Registration #13	2016-03-03	38.051 mi
Registration #14	2016-03-03	38.051 mi
Registration #15	2016-03-03	38.051 mi
Registration #16	2016-03-03	38.051 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1795 mm
Height	1440 mm
Length	4755 mm
Wheel base	2725 mm
Max. allowed weight	1975 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	LF 10510869