



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 SE SPORT V50
Colour	Silver
Year of manufacture	-
Top speed	124 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	165 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	28.8 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.7 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-24
Pictures	42
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #19	2021-03-01 14:32
MOT test number	970977070194
Result	✓ Passed
Next expiry date	2022-03-01
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #18	2021-02-23 12:02
MOT test number	962492892737
Result	✗ Failed
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail	Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail	Central Upper Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail	Emissions not tested (8.2.1.2 (d))

**MOT #17**

2020-02-27 13:07

MOT test number

546452741871

Result

✓ Passed

- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Rear exhaust mounts corroded
- Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16

2019-02-26 08:54

MOT test number

842983302094

Result

✓ Passed

- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #15**

2019-02-25 12:22

MOT test number

881054059998

Result

✗ Failed

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Front Lower Suspension arm pin or bush excessively worn rearmost (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #14**

2018-03-02 11:07

MOT test number

816312867637

Result

✓ Passed

Advice Nearside Rear tyre smooth on inner edge**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**Advice** Offside Front Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #13**

2017-01-17 17:24

MOT test number

411937139628

Result

✓ Passed

**MOT #12**

2016-08-25 10:48

MOT test number

765343856287

Result

✓ Passed

Advice

Offside Front Tyre worn close to the legal limit 2mm (4.1.E.1)

Advice

Nearside Front Tyre worn close to the legal limit 2mm (4.1.E.1)

MOT #11

2016-08-25 09:06

MOT test number

433571455232

Result

✗ Failed

Advice

Nearside Front Tyre worn close to the legal limit 2mm (4.1.E.1)

Fail

Nearside Rear Exhaust system not adequately supported (7.1.1)

Advice

Offside Front Tyre worn close to the legal limit 2mm (4.1.E.1)

MOT #10

2015-09-04 09:08

MOT test number

903682301754

Result

✓ Passed

Advice

Offside Rear Brake pad(s) wearing thin (3.5.1g)

Advice

Nearside Rear Brake pad(s) wearing thin (3.5.1g)

MOT #9

2015-09-04 09:08

MOT test number

100448217414

Result

✗ Failed

Advice

Nearside Rear Brake pad(s) wearing thin (3.5.1g)

Pass with rectification

Nearside Rear Direction indicator incorrect colour (1.4.A.2f)

Advice

Offside Rear Brake pad(s) wearing thin (3.5.1g)



MOT #8	2014-09-02 14:44
---------------	------------------

MOT test number	519345444290
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #7	2013-09-06 10:52
---------------	------------------

MOT test number	315669043469
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2013-09-06 10:52
---------------	------------------

MOT test number	509479543235
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Offside Rear Registration plate lamp not working (1.1.C.1d)
--------------------------------	---

MOT #5	2012-07-05 08:52
---------------	------------------

MOT test number	979517782142
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2012-07-05 08:52
---------------	------------------

MOT test number	158607082102
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Nearside Rear Registration plate lamp not working (1.1.C.1d)
--------------------------------	--

MOT #3	2011-06-21 16:00
---------------	------------------

MOT test number	677332671174
------------------------	--------------

Result	✓ Passed
---------------	----------



MOT #2	2011-06-21 09:36
MOT test number	505692471166
Result	✗ Failed
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)

MOT #1	2010-05-10 09:49
MOT test number	950670830129
Result	✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-06-05
Last registration	2021-03-01
Complete history	See info



Registration #1	2007-06-05	14 mi
Registration #2	2010-05-10	30.989 mi
Registration #3	2011-06-21	37.281 mi
Registration #4	2011-06-21	37.281 mi
Registration #5	2012-07-05	41.661 mi
Registration #6	2013-09-06	48.745 mi
Registration #7	2014-09-02	55.266 mi
Registration #8	2015-09-04	60.651 mi
Registration #9	2015-09-04	60.651 mi
Registration #10	2016-08-25	67.001 mi
Registration #11	2016-08-25	67.001 mi
Registration #12	2016-08-25	67.001 mi
Registration #13	2016-08-25	67.001 mi
Registration #14	2016-08-25	67.001 mi
Registration #15	2016-08-25	67.001 mi
Registration #16	2016-08-25	67.001 mi
Registration #17	2016-08-25	67.001 mi
Registration #18	2016-08-25	67.001 mi
Registration #19	2016-08-25	67.001 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4514 mm
Wheel base	2640 mm
Kerb weight	1402 kg
Max. allowed weight	1890 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	89721