





report date: 2024-03-28

## General information

Make	RENAULT
Model	MASTER LH35 DCI H/R P/V
Colour	Grey
Year of manufacture	2013
Top speed	82 mph
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	150 BHP
Max. torque	350 Nm at 2.750 rpm
Engine capacity	2.298 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.3 mpg
Consumption extra urban	37.1 mpg
Consumption combined	33.6 mpg
CO2 emission	223 g/km
CO2 label	K



CarCheck.co.uk page 1/10



report date: 2024-03-28

# Internet history

## Entry 1

Date 2022-06-21

Pictures 8

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/10



report date: 2024-03-28

# MOT history

MOT expiry date	2023-07-18
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	7
Total items failed	5

MOT #9	2022-07-19 08:52
MOT test number	919470930958
Result	<b>✓</b> Passed
Next expiry date	2023-07-18

MOT #8		2021-11-01 11:22
MOT test	number	200633340335
Result		✓ Passed
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorate	red (6.1.7 (g) (i))
Advice	Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))	
Minor	Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a)	(i))

MOT #7		2020-10-23 10:05
MOT test number	er	109466069397
Result		✓ Passed
MOT #6		2020-10-23 09:42
MOT test number	er	293918386427
Result		<b>×</b> Failed
DANGEROUS	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

CarCheck.co.uk page 3/10



report date: 2024-03-28

MOT #5	2019-10-31 13:02
MOT test number	608916360050
Result	✓ Passed
MOT #4	2018-10-08 10:08
MOT test number	432351265340
Result	✓ Passed
MOT #3	2018-10-08 10:08
MOT test number	657170491934
Result	<b>★</b> Failed
Pass with rectification Nearside Stop lamp(s) not working (4.3.	1 (a) (ii))

MOT #2	2017-09-25 13:37
MOT test number	617111843642
Result	<b>✓</b> Passed
Advice N/s/f windscreen damaged	

MOT #1	2017-09-21 09:49
MOT test number	751044739594
Result	🗙 Failed
Fail Central Rear Stop lamp not working (1.2.1b)	
Advice N/s/f windscreen damaged	
Fail Windscreen washer provides insufficient washer liquid (8.2.3)	
Fail Nearside Rear Rear position lamp(s) not working (1.1.A.3b)	
Advice N/s side marker not working	
Fail Offside Front Body has a sharp edge caused by damage side repeater lens broke	n (6.1.C.1)

CarCheck.co.uk page 4/10



report date: 2024-03-28

## Tax & MOT check

Tax expired: 12 June 2022



**Х** МОТ

Expired: 18 July 2023

Tax statusExpired at 12 June 2022Days left688 days too lateMOT expiry date18 July 2023

Full MOT history See MOT history

## Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 5/10



report date: 2024-03-28

## Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/10



report date: 2024-03-28

# Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
***********	
manus .	
************	
	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	NK SIN
Plate since	
	More info >

CarCheck.co.uk page 7/10



report date: 2024-03-28

## Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 8/10



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-08-12
Last registration	2022-07-19
Complete history	See info



Registration #1	2013-08-12	23 mi
Registration #2	2017-09-21	48.894 mi
Registration #3	2017-09-25	48.902 mi
Registration #4	2018-10-08	52.952 mi
Registration #5	2018-10-08	52.952 mi
Registration #6	2019-10-31	65.187 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 mg

More info >

CarCheck.co.uk page 9/10



report date: 2024-03-28

## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Dimensions & weight

Width	2470 mm
Height	2744 mm
Length	6198 mm
Kerb weight	1970 kg
Max. allowed weight	3500 kg

# Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	C018526

CarCheck.co.uk page 10/10