



report date: 2024-03-29

## General information

Make	VOLVO
Model	V40 D2 INSCRIPTION
Colour	Black
Year of manufacture	2017
Top speed	118 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	118 BHP
Max. torque	280 Nm at 1.500 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	101 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-02-06
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://autoonline.co.uk)



MOT history

MOT expiry date	2024-11-25
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	19
Total items failed	1

MOT #7	2023-11-23 09:53
MOT test number	984112083172
Result	✓ Passed
Next expiry date	2024-11-25
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))

MOT #6	2022-11-26 12:19
MOT test number	454120438397
Result	✓ Passed
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords Outer wall (5.2.3 (d) (i))
Advice	Rear Both rubber bump stops missing
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Offside Rear Tyre has a cut but not deep enough to reach the ply or cords In tread (5.2.3 (d) (i))
Advice	Offside Front Tyre slightly damaged Outer wall (5.2.3 (d) (ii))

**MOT #5** 2022-11-24 10:50**MOT test number** 358520842973**Result** ✗ Failed

- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords Outer wall (5.2.3 (d) (i))
- Advice** Offside Front Tyre slightly damaged Outer wall (5.2.3 (d) (ii))
- MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords In tread (5.2.3 (d) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Both rubber bump stops missing

**MOT #4** 2021-11-24 09:02**MOT test number** 809880305351**Result** ✓ Passed

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #3** 2020-11-25 12:50**MOT test number** 356182761625**Result** ✓ Passed**MOT #2** 2020-10-07 09:48**MOT test number** 309742155606**Result** ✓ Passed

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))



MOT #1	2020-10-07 09:48
MOT test number	671594303312
Result	✗ Failed
Pass with rectification	Front Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
25 November 2024

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	306
<b>MOT expiry date</b>	25 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>First licence fee (12 months)</b>	£ 185,00,-
<b>First licence fee diesel non RDE2 tested (12 months)</b>	£ 210,00,-
<b>Standard rate (12 months)</b>	£ 180,00,-
<b>Standard rate (6 months)</b>	£ 99,00,-
<b>Premium rate (12 months)</b>	£ 570,00,-
<b>Premium rate (6 months)</b>	£ 313,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>YY67FEO</b>
Plate since	2019-09-29
Current registration	<b>YY67FEO</b>
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-10-10
Last registration	2023-11-23
Complete history	<a href="#">See info</a>



Registration #1	2017-10-10	26 mi
Registration #2	2020-10-07	38.106 mi
Registration #3	2020-10-07	38.106 mi
Registration #4	2020-11-25	38.702 mi
Registration #5	2023-11-23	38.702 mi
Registration #6	2023-11-23	38.702 mi
Registration #7	2023-11-23	38.702 mi
Registration #8	2023-11-23	38.702 mi
Registration #9	2023-11-23	38.702 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1857 mm
Height	1439 mm
Length	4369 mm
Wheel base	2647 mm
Kerb weight	1439 kg
Max. allowed weight	1995 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1956349